

UNCLASSIFIED

AD NUMBER

ADB024228

LIMITATION CHANGES

TO:

Approved for public release; distribution is unlimited.

FROM:

Distribution authorized to U.S. Gov't. agencies only; Test and Evaluation; APR 1977. Other requests shall be referred to Air Force Materials Laboratory, Attn: MBE, Wright-Patterson AFB, OH 45433.

AUTHORITY

AFWAL ltr, 21 sep 1982

THIS PAGE IS UNCLASSIFIED

UNCLASSIFIED

AD B024228

AUTHORITY: AFWAL
17r, 21 Sep 82



UNCLASSIFIED

AFML-TR-77-83

20


ADB024228

TEMPERATURE CONTROLLED QUARTZ CRYSTAL MICROBALANCE SYSTEM

FARADAY LABORATORIES INC.
LA JOLLA, CALIFORNIA 92037

MAY 3, 1977

TECHNICAL REPORT AFML-TR-77-83
Final Report for Period June 2, 1975 to May 3, 1977



Distribution limited to U.S. Government agencies only; test and evaluation; April 1977. Other requests for this document must be referred to the Air Force Materials Laboratory, Nonmetallic Materials Division, Elastomers and Coatings Branch, AFML/MBE, Wright-Patterson Air Force Base, Ohio 45433.

NYJ.
DDC FILE COPIES
DD

AIR FORCE MATERIALS LABORATORY
AIR FORCE WRIGHT AERONAUTICAL LABORATORIES
AIR FORCE SYSTEMS COMMAND
WRIGHT-PATTERSON AIR FORCE BASE, OHIO

NOTICE

When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

This technical report has been reviewed and is approved for publication.

R. A. Winn

R. A. WINN
Project Monitor

FOR THE DIRECTOR

J. K. Sieron

J. K. SIERON, Chief
Elastomers and Coatings Branch
Nonmetallic Materials Division

Copies of this report should not be returned unless return is required by security considerations, contractual obligations, or notice on a specific document.

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE			READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER AFML-TR-77-83	2. GOV'T ACQUISITION NO. Optical rep't.	3. RECIPIENT'S CATALOG NUMBER 2 Jun 75-3 May 77	4. TYPE OF REPORT & PERIOD COVERED Final, 6/2/75 - 5/9/77
4. TITLE (and Subtitle) TEMPERATURE CONTROLLED QUARTZ CRYSTAL MICROBALANCE SYSTEM,	5. PERFORMING ORG. REPORT NUMBER FAR-D-010-77	6. CONTRACT OR GRANT NUMBER(s) F33615-75-C-5171	7. AUTHOR(s) D. J. McKeown, C. R. Claysmith, W. T. Breckenridge, Jr. R. S. Dummer
9. PERFORMING ORGANIZATION NAME AND ADDRESS Faraday Laboratories Inc. P. O. Box 2308 La Jolla, CA 92038	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS IL 10071 1700	11. CONTROLLING OFFICE NAME AND ADDRESS Elastomers & Coatings Branch (MBE), Nonmetallic Materials Division, Air Force Materials Laboratory, Wright-Patterson Air Force Base, Ohio	12. REPORT DATE 11/3 May 77
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)	13. NUMBER OF PAGES 80 (1292 p.)	15. SECURITY CLASS. (If applicable) Unclassified	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Distribution limited to U.S. Government agencies only; test and evaluation; April 1977. Other requests for this document must be referred to the Air Force Materials Laboratory, Nonmetallic Materials Division, Elastomers and Coatings Branch, AFML/MBE, Wright Patterson Air Force Base, Ohio 45433.			
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)			
18. SUPPLEMENTARY NOTES None			
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Temperature Controlled Quartz Crystal Microbalance (TQCM), TQCM System, Surface Contamination, 15-MHz Crystal, Optical Polish, Thermal Model, Second-Surface Mirrors, Radiator, Electronics and Command Logic			
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The TQCM system is designed to measure surface contamination as a function of temperature on the SCATHA satellite. The TQCM system consists of two radiatively-cooled Heads and a Controller. Each Head contains a removable high-sensitivity (1.56×10^{-9} g/cm ²) mass sensor, temperature probe and heater. By ground command, the Controller can set both sensors to operate simultaneously at +100, +30, 0, -30, -60°C ±1°C or free run. Computer thermal modeling shows that a free running Head pointed into deep space will reach an equilibrium temperature of -163°C.			

DD FORM 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

388436

39 CM

100

Dace

97% power

156

NOT
Preceding Page BLANK - FILMED

PREFACE

This report was prepared by D. McKeown, C.R. Claysmith W.T. Breckenridge, Jr. and R.S. Dummer of Faraday Laboratories Inc., La Jolla, CA 92038, under Contract F33615-75-C-5171. This program was initiated under IL1R0071, Laboratory Director's Funds. The program was administered under the direction of the Elastomers and Coatings Branch (MBE), Nonmetallic Materials Division, Air Force Materials Laboratory, Wright-Patterson Air Force Base, Ohio, with Mr. Robert A. Winn serving as project engineer.

This report covers research and development conducted during the period of June 1975 to December 1976.

ACCESSION NO.	
FTIS	White Section <input type="checkbox"/>
SCO	Buff Section <input checked="" type="checkbox"/>
UNARMED	<input type="checkbox"/>
JUSTIFICATION	
DISTRIBUTION/AVAILABILITY CODES	
B&W	AVAIL. NRD/OF SPECIAL
B	




TABLE OF CONTENTS

	<u>Page</u>
I INTRODUCTION	1
II TQCM SYSTEM	1
III THERMAL ANALYSIS	1
IV TQCM ELECTRONICS	7
V CALIBRATION	29
VI COMMAND LOGIC	56
REFERENCES	56
APPENDIX - TQCM SYSTEM MECHANICAL DESIGN	57

List of Illustrations

<u>Figure</u>	<u>Caption</u>	<u>Page</u>
1	TQCM System Specifications	2
2	TQCM System without RPA Installed	3
3	TQCM Head Showing Electronics and Super Insulation	4
4	TQCM Controller Side View	5
5	TQCM Controller Showing Freq/Volt Converters Board No. 125 and Serial Command Decoder Board No. 128	6
6	TQCM Head Design	8
7	TQCM Sensor Crystal Cool-Down When Pointed into Deep Space	9
8	TQCM Cool-Down When Viewing Sun at 1 RPM	10
9	Sensor Temperature and Heater Power for Space Oriented TQCM Commanded to -60°C	11
10	Sensor Temperature and Heater Power for Space Oriented TQCM Commanded to -30°C	12
11	Sensor Temperature and Heater Power for Space Oriented TQCM Commanded to 0°C	13
12	Sensor Temperature and Heater Power for Space Oriented TQCM Commanded to +30°C	14
13	Sensor Temperature and Heater Power for Space Oriented TQCM Commanded to +100°C	15
14	Sensor Temperature and Heater Power for Sun Oriented TQCM Commanded to -60°C	16

List of Illustrations (continued)

<u>Figure</u>	<u>Caption</u>	<u>Page</u>
15	Sensor Temperature and Heater Power for Sun Oriented TQCM Commanded to -30°C	17
16	Sensor Temperature and Heater Power for Sun Oriented TQCM Commanded to 0°C	18
17	Sensor Temperature and Heater Power for Sun Oriented TQCM Commanded to +30°C	19
18	Sensor Temperature and Heater Power for Sun Oriented TQCM Commanded to +100°C	20
19	TQCM System Electronics Interconnect	22
20	TQCM Head Electronics Block Diagram	23
21	TQCM Controller Electronics Block Diagram	24
22	TQCM Head Matched 15-MHz Oscillators	25
23	TQCM Head Mixer and Output Amplifier	26
24	TQCM Controller Freq/Volt Converters	27
25	TQCM Controller Heater Driver	28
26	TQCM Controller Temp Bridge	30
27	TQCM Controller Serial Command Decoder	31
28	TQCM Controller Decoder Relay Network	32
29	TQCM Controller Power Supply	33
30	TQCM Sensors Freq vs Temperature Calibration	35
31	TQCM 15-MHz Sensor Calibration	49

List of Illustrations (continued)

<u>Figure</u>	<u>Caption</u>	<u>Page</u>
32	TQCM Head H-1 High-Sensitivity Analog Mass Calibration	50
33	TQCM Head H-1 Low-Sensitivity Analog Mass Calibration	51
34	TQCM Head H-1 Temp Calibration	52
35	TQCM Head H-2 High-Sensitivity Analog Mass Calibration	53
36	TQCM Head H-2 Low-Sensitivity Analog Mass Calibration	54
37	TQCM Head H-2 Temp Calibration	55
38	TQCM Head	58
39	TQCM Head Radiator Plate	59
40	TQCM Head Section Diagrams (Radiator Plate)	60
41	TQCM Head Hole and Rib Layout (Radiator Plate)	61
42	TQCM Head Mirror Placement and Grounding Slcts	62
43	TQCM Head Base Plate	63
44	TQCM Head Hole Layout (Base Plate)	64
45	TQCM Head View (Base Plate)	65
46	TQCM Head Assembly Parts I	66
47	TQCM Head Assembly Parts II	67
48	TQCM Head Assembly Parts III	68

List of Illustrations (continued)

<u>Figure</u>	<u>Caption</u>	<u>Page</u>
49	TQCM Head Electronics Package	69
50	TQCM Controller	70
51	TQCM Controller Base	71
52	TQCM Controller Base Hole Layout	72
53	TQCM Controller Cover	73
54	TQCM Controller Cover Hole Layout	74
55	TQCM Controller Assembly Parts I	75
56	TQCM Controller Assembly Parts II	76
57	TQCM Controller Assembly Parts III	77
58	TQCM Controller Assembly Parts IV	78
59	TQCM Controller Module Placement	79
60	TQCM Sensor Assembly	80

List of Tables

<u>Table</u>	<u>Caption</u>	<u>Page</u>
1	Freq vs Temp Calibration of TQCM 15-MHz Sensor Crystals in 1×10^{-7} Torr Vacuum	34
2	TQCM Freq/Volt Converter Output at 0°C Ambient for Input Power Voltage of +28Vdc $\pm 4V$. Sensor Beat Freq at Zero Loading 2KHz	36
3	TQCM Freq/Volt Converter Output at +20°C Ambient for Input Power Voltage of +28Vdc $\pm 4V$. Sensor Beat Freq at Zero Loading 2KHz	37
4	TQCM Freq/Volt Converter Output at +30°C Ambient for Input Power Voltage of +28Vdc $\pm 4V$. Sensor Beat Freq at Zero Loading 2KHz	38
5	TQCM Freq/Volt Converter Output at +50°C Ambient for Input Power Voltage of +28Vdc $\pm 4V$. Sensor Beat Freq at Zero Loading 2KHz	39
6	TQCM Temp Outputs for Different Input Power Voltages at 0°C Ambient	40
7	TQCM Temp Outputs for Different Input Power Voltages at +20°C Ambient	41
8	TQCM Temp Outputs for Different Input Power Voltages at +30°C Ambient	42
9	TQCM Temp Outputs for Different Input Power Voltages at +50°C Ambient	43
10	TQCM Commanded and Operating Temp for Different Input Voltages and Ambient Temperatures	44
11	Power Supply Calibration at 0°C Ambient	45

List of Tables (continued)

<u>Table</u>	<u>Caption</u>	<u>Page</u>
12	Power Supply Calibration at +20°C Ambient	46
13	Power Supply Calibration at +30°C Ambient	47
14	Power Supply Calibration at +50°C Ambient	48
15	TQCM System Serial Command Logic	56

SUMMARY

The Final Report describes the design and construction of a Temperature-Controlled Quartz Crystal Microbalance (TQCM) system for flight on the SCATHA satellite. The TQCM system consists of two radiatively-cooled Heads and a Controller. Each Head contains a removable high-sensitivity mass sensor, temperature probe and heater. By ground command, the Controller can set both sensors to operate simultaneously at +100, +30, 0, -30, -60°C $\pm 1\text{ }^{\circ}\text{C}$ or free run. For free run, a Head reaches an equilibrium temperature depending on its view of space. For example, results from a computer thermal model show a Head periodically viewing the sun and deep space will reach about -67°C while a Head continuously pointed into deep space will reach about -163°C.

TQCM inputs are temperature commands, power, enable and clock. Outputs for each Head are high and low-sensitivity mass and sensor temperature 0 to 5 volt analogs and frequency vs mass.

The mass sensors are instrumented with low-power dissipation 15-MHz, aluminum plated, optically-polished quartz crystals. Mass sensitivity is $1.56 \times 10^{-9} \text{ g/cm}^2\text{-Hz}$ which is over two times greater than 10-MHz crystals now being used in space.

Each Head is $5.7 \times 5.7 \times 3.9$ in and weighs 1.4 lb.

The Controller is $4.8 \times 5.6 \times 3.3$ in and weighs 1.8 lb.

The TQCM system operates on +28 ± 4 Vdc at 2.142 W for heaters OFF and 5.07 W for heaters ON.

A structure is provided in each Head for mounting a potential analyzer to determine the effects of spacecraft charge on surface contamination.

1.0 Introduction

The TQCM system design is based on the Cryogenic QCM¹ (CQCM) constructed for flight on the NASA Shuttle. The CQCM is radiatively-cooled and operates at minimum temperatures to measure water vapor contamination.

The TQCM makes use of the CQCM thermal modeling, high-sensitivity, removable mass sensors and low-power dissipation electronics. The TQCM has the added capability of temperature control by command.

The TQCM design incorporates temperature commands because of the need to measure various species of contamination including water vapor as a function of temperature. The TQCM sensor temperature can be set by command to operate at +100, +30, 0, -30, -60°C ±1°C or free run.

2.0 TQCM System

The TQCM system size and weight are shown in Figure 1. The enlarged view of the sensor shows location of the quartz crystals.

A photograph of the system is shown in Figure 2. The small tabs at the four corners of each mirror are for electrically grounding the radiator to the satellite. The square region in the center of the Head is for mounting a potential analyzer for studying surface contamination as a function of spacecraft charge.

Different views of the Head and Controller are shown in Figures 3, 4 and 5.


3.0 Thermal Analysis

The amount of power, W, radiated by a surface is defined by

$$W = \epsilon\sigma (T_1^4 - T_0^4)$$

where ϵ is surface emittance, σ the Stefan-Boltzman constant ($5.67 \times 10^{-9} \text{ W/m}^2\text{K}^4$) and T_1 and T_0 are respectively the surface temperature and the temperature of space in °K.

The power radiated by a surface (140°K) into space (4°K) is 2.18 mW/cm². For a 100 cm² radiator, suitable for cooling a TQCM, the



Enlarged view

SPECIFICATIONS

Head: 5.7 x 5.7 x 3.9 in
1.4 lb (without RPA)

Controller: 4.8 x 5.6 x 3.3 in
1.8 lb

Power: 28 Vdc ±4
2.142 W Heaters OFF
5.07 W Heaters ON




Figure 1 TQCM System Specifications

FIGURE 2 TQCM SYSTEM WITHOUT RPA INSTALLED




FIGURE 3 TQCM HEAD SHOWING ELECTRONICS AND SUPER INSULATION





FIGURE 4 TQCM CONTROLLER SIDE VIEW






FIGURE 5 TQCM CONTROLLER SHOWING FREQ/VOLT CONVERTERS BOARD No. 125
AND SERIAL COMMAND DECODER BOARD No. 128

power is 213 mW. In practice, the effective cooling is much less because:

- a) Surface emittance is less than unity
- b) Backside of the radiator will absorb heat from the spacecraft
- c) Conduction of heat from the spacecraft to the radiator
- d) Oscillating quartz crystal sensor dissipate power

The optimum TQCM Head design was determined by computer modeling.² Several computer runs were made on Head designs using various materials for its construction and different levels of power dissipations in the crystal sensors.

The final Head design is shown in Figure 6. The Head contains the radiant cooler, mass sensors, oscillators and output amplifier. The radiant cooler is a plane surface constructed from aluminum. The sensors are mounted in a well machined in the radiator. Second-surface quartz silver plated mirrors are attached with RTV to the radiator.* The mirror front surfaces are coated with a conducting layer of indium oxide for grounding purposes. The mirrors have a solar absorptance $\alpha \approx 0.08$ and a thermal emittance $\epsilon \approx 0.80$. The radiator is attached to the base plate by four high-strength fiberglass-epoxy laminate standoffs. The electronic unit is connected to the crystal sensor by 0.005 in diameter Stablohm leads to provide thermal isolation.

Radiative heat exchange from spacecraft to the radiator is minimized using a stacked multilayer superinsulation of gold plated Kapton held in place beneath the radiator by a Teflon screen.

After the Head design was fixed, its operation in space was determined by computer analysis. Calculated minimum equilibrium temperatures are shown in Figure 7 for a Head viewing space and in Figure 8 for viewing the sun and space at 1 RPM.

The heating powers required to maintain the space oriented Head at various set temperatures are shown in Figures 9 - 13. The sensor operates at a higher temperature than the set temperature because of its power dissipation.

The heating powers required to maintain the 1 RPM sun oriented Head at various set temperatures are shown in Figures 14 - 18. The sensor operates above set temperature because of its power dissipation.

4.0 TQCM Electronics

The goal of the electronics design was to minimize power dissipation in the TQCM so as not to excessively load the radiant cooler.

* Mirror attachment was made by the Aerojet Electro Systems Co. through the assistance of Dr. M.K. Barsch.




Figure 6 TQCM Head Design




Figure 7 TQCM Sensor Crystal Cool-Down When Pointed into Deep Space




Figure 8 TQCM Cool-Down When Viewing Sun at 1 RPM




Figure 9 Sensor temperature and heater power for space oriented TQCM commanded to -60°C




Figure 10 Sensor temperature and heater power for space oriented TQCM commanded to -30°C




Figure 11 Sensor temperature and heater power for space oriented TQCM commanded to 0°C




Figure 12 Sensor temperature and heater power for space oriented TQCM commanded to +30°C




Figure 13 Sensor temperature and heater power for space oriented TQCM commanded to +100°C




Figure 14 Sensor temperature and heater power for sun oriented TQCM commanded to -60°C




Figure 15 Sensor temperature and heater power for sun oriented TQCM commanded to -30°C




Figure 16 Sensor temperature and heater power for sun oriented TQCM commanded to 0°C




Figure 17 Sensor temperature and heater power for sun oriented TQCM commanded to +30 °C




Figure 18 Sensor temperature and heater power for sun oriented TQCM commanded to +100 °C

The TQCM system interconnections are shown in Figure 19.
The Head electronics block diagram is shown in Figure 20.
The Controller electronics block diagram is shown in Figure 21.

4.1 Oscillators

Oscillators are designed with a wide band width to operate 15-MHz crystal sets.* The power dissipation for the oscillators is 5 mW. The oscillator diagram is shown in Figure 22.

4.2 Beat Frequency

The oscillators drive a mixer-beat-frequency operational amplifier having a low impedance high-gain output. The total power dissipation of the TQCM oscillators and operational amplifier is only 16 mW and represents a reduction of better than 2/3 over the best QCM now available. The frequency output of the amplifier is proportional to sensor crystal contamination loading. This frequency is provided as an output for direct monitoring of contamination. The frequency is also fed into a converter to provide an analogue output for spacecraft telemetry. The mixer and output amplifier diagram is shown in Figure 23.

4.3 Frequency Converter

The analogue output of frequency is provided by a two frequency-analogue (F/A) converter. The high and low sensitivity converters are shown in Figure 24. Capacitor/resistor networks on the outputs protect the converters from damage by telemetry voltage surges.

4.4 Heater Driver

The sensor heater requires about 1 W during operation. The heater driver shown in Figure 25 provides this heavy power.

4.5 Temperature Bridge

The temperature of mass sensors is monitored by a precision helium-filled platinum thermometer linear to 0.5%. The bridge output

* Crystal set dissipates < 100 μ W depending on drive level






Figure 19




TQCM HEAD ELECTRONICS BLOCK DIAGRAM

Figure 20



TQCM CONTROLLER ELECTRONICS BLOCK DIAGRAM




X1 - 15 MHz QUARTZ CRYSTAL (SENSOR)

X2 - 15 MHz QUARTZ CRYSTAL (REF)


TQCM HEAD MATCHED 15-MHz OSCILLATORS

Figure 22




TQCM HEAD MIXER AND OUTPUT AMPLIFIER

Figure 23



TQCM CONTROLLER FREQ/VOLT CONVERTERS

Figure 24



TQCM CONTROLLER HEATER DRIVER

Figure 25

provided the signal to maintain a commanded set temperature. The bridge is shown in Figure 26.

4.6 Command Electronics

The decoder for input temperature commands is shown in Figure 27. The Zener capacitor network on the clock, enable, and data lines protects the decoder from input voltage surges.

The relay network is driven by the decoder for operating the heater driver. It is shown in Figure 28.

4.7 Power Supply

The TQCM requires a highly stable DC/DC isolation from satellite +28 ± 4 Vdc power. Separate high and low power outputs for electronics and heaters are needed. The high-efficient, switching supply, manufactured for Faraday Laboratories Inc. by Transistor Devices Inc., is shown in Figure 29.

5.0 Calibration

5.1 Mass Sensor

The heart of the TQCM is its high mass sensitivity 15-MHz mass sensor. The design goal for sensor temperature vs frequency stability was ± 75 between -60 and +60°C. This difficult objective was exceeded for the two sensors. Table 1 shows the matched crystals to have stabilities of ± 35 Hz and ± 14 Hz between -60 and +60°C.


Frequency vs temperature plots for the crystal sets used in TQCM Heads 1 and 2 respectively are shown between -60 and +100°C in Figure 30.

After the sensors were calibrated, the sensor crystals were overplated with aluminum to give the matched set a beat frequency of 2kHz required for driving the F/A converters.

5.2 Controller


Calibration data of the TQCM Controller outputs for various input voltages at various ambient temperatures are shown in Tables 2 - 14.

The tabulated calibration data are plotted in Figures 31 - 37 for TQCM Heads 1 and 2. Ambient temperature variations and input voltage changes are not called out in the figures. Changes in voltage and temperature produce Controller output changes of less than a few per cent and are




TQCM CONTROLLER TEMP BRIDGE

Figure 26



TQCM CONTROLLER SERIAL COMMAND DECODER

Figure 27



TQCM CONTROLLER DECODER RELAY NETWORK

Figure 28




Figure 29

Table 1 Freq vs Temp Calibration of TQCM 15-MHz Sensor Crystals in 1×10^{-7} Torr Vacuum

Matched Crystal Set No. 1 Installed in TQCM Head No. 1								
Δ Beat Freq with Temp Decrease from +20°C								
Crystal	+20°C		0°C		-20°C		-40°C	
	Freq (Hz)	Δ Beat (Hz)						
494 (Sensor)	15,095,145	15,095,082	15,095,087	-19	15,094,837	-22	15,094,230	-36
333 (Ref)	15,082,204	15,082,151	15,082,159	-19	15,081,923	-22	15,081,346	-66
Δ Beat Freq with Temp Increase from +20°C								
Crystal	+20°C		+40°C		+60°C		+80°C	
	Freq (Hz)	Δ Beat (Hz)						
494 (Sensor)	15,095,030	15,095,002	15,094,937	+4	15,094,882	-8	15,095,290	-46
333 (Ref)	15,081,994	15,081,962	15,081,909	+4	15,081,892	-8	15,082,269	-15

Matched Crystal Set No. 2 Installed in TQCM Head No. 2								
Δ Beat Freq with Temp Decrease from +20°C								
Crystal	+20°C		0°C		-20°C		-40°C	
	Freq (Hz)	Δ Beat (Hz)						
457 (Sensor)	15,082,128	15,082,123	15,082,111	+15	15,081,908	+11	15,081,241	-4
324 (Ref)	15,082,284	15,082,294	15,082,278	+15	15,082,060	-4	15,081,394	-13

Matched Crystal Set No. 3 Installed in TQCM Head No. 3								
Δ Beat Freq with Temp Increase from +20°C								
Crystal	+20°C		+40°C		+60°C		+80°C	
	Freq (Hz)	Δ Beat (Hz)						
457 (Sensor)	15,082,018	15,082,005	15,081,976	+3	15,081,993	-7	15,082,105	+2
324 (Ref)	15,082,209	15,082,199	15,082,160	+3	15,082,186	-7	15,082,324	+38




Figure 30 TQCM Sensors Frequency vs Temperature Calibration

Table 2 TQCM Freq/Volt Converter Output at 0°C Ambient for Input Power Voltage of +28 Vdc ± 4V. Sensor Beat Freq at Zero Loading 2KHz

Sensor Beat Freq Change	Mass Loading Change	Hi-Sens. Out. No. 1	Lo-Sens. Out. No. 1	Hi-Sens. Out. No. 2	Lo-Sens. Out. No. 2
(Hz)	(g/cm ² × 10 ⁻⁶)	(V)	(V)	(V)	(V)
-200	0.312	4.87	5.07	4.97	5.05
-150	0.234	4.72	5.07	4.80	5.05
-100	0.156	4.56	5.06	4.64	5.05
-50	0.078	4.40	5.06	4.48	5.04
0	0	4.24	5.06	4.31	5.04
100	0.156	3.94	5.05	4.00	5.03
200	0.312	3.62	5.04	3.67	5.02
300	0.468	3.31	5.03	3.35	5.01
400	0.624	2.99	5.03	3.02	5.00
500	0.780	2.67	5.02	2.69	5.00
600	0.936	2.36	5.01	2.37	4.99
700	1.092	2.04	5.00	2.04	4.98
800	1.248	1.73	5.00	1.72	4.98
900	1.404	1.41	4.99	1.39	4.97
1,000	1.560	1.09	4.98	1.06	4.96
1,100	1.716	.77	4.97	.73	4.95
1,200	1.872		4.96		4.94
3,000	4.680		4.83		4.81
8,000	12.480		4.43		4.41
18,000	28.080		3.66		3.63
28,000	43,680		2.88		2.85
38,000	59,280		2.11		2.07
48,000	74,880		1.34		1.29
58,000	90,480		.68		.66
59,000	92.040		.63		.62
60,000	93.60		.57		.56

Table 3 TQCM Freq/Volt Converter Output at +20°C Ambient for Input Power Voltage of +28 Vdc \pm 4V. Sensor Beat Freq at Zero Loading 2KHz

<u>Sensor Beat Freq Change</u>	<u>Mass Loading Change</u>	<u>Hi-Sens. Out. No. 1</u>	<u>Lo-Sens. Out. No. 1</u>	<u>Hi-Sens. Out. No. 2</u>	<u>Lo-Sens. Out. No. 2</u>
(Hz)	(g/cm ² \times 10 ⁻⁶)	(V)	(V)	(V)	(V)
-200	0.312	5.06	5.09	5.15	5.07
-150	0.234	4.90	5.09	5.00	5.07
-100	0.156	4.75	5.08	4.83	5.06
-50	0.078	4.60	5.08	4.68	5.06
0	0	4.45	5.07	4.52	5.06
100	0.156	4.14	5.07	4.20	5.05
200	0.312	3.84	5.06	3.89	5.04
300	0.468	3.53	5.05	3.57	5.03
400	0.624	3.22	5.05	3.25	5.03
500	0.780	2.92	5.04	2.94	5.02
600	0.936	2.61	5.03	2.62	5.01
700	1.092	2.30	5.02	2.31	5.00
800	1.248	1.99	5.01	1.99	4.99
900	1.404	1.68	5.01	1.67	4.99
1,000	1.560	1.38	5.00	1.35	4.90
1,100	1.716	1.07	4.99	1.04	4.97
1,200	1.872	.76	4.98		4.96
3,000	4.680		4.84		4.82
8,000	12.480		4.45		4.43
18,000	28.080		3.67		3.65
28,000	43.680		2.90		2.86
38,000	59.280		2.12		2.09
48,000	74.880		1.35		1.30
58,000	90.480		.68		.66
59,000	92.040		.63		.62
60,000	93.60		.56		.55

Table 4 TQCM Freq/Volt Converter Output at +30°C Ambient for Input Power Voltage of +28 Vdc ± 4V. Sensor Beat Freq at Zero Loading 2KHz

<u>Sensor Beat Freq Change</u>	<u>Mass Loading Change</u>	<u>Hi-Sens. Out. No. 1</u>	<u>Lo-Sens. Out. No. 1</u>	<u>Hi-Sens. Out. No. 2</u>	<u>Lo-Sens. Out. No. 2</u>
(Hz)	(g/cm ² × 10 ⁻⁶)	(V)	(V)	(V)	(V)
-200	0.312	5.05	5.09	5.15	4.94
-150	0.234	4.90	5.09	4.99	5.08
-100	0.156	4.74	5.09	4.84	5.07
-50	0.078	4.59	5.08	4.67	5.07
0	0	4.44	5.08	4.52	5.06
100	0.156	4.14	5.07	4.21	5.05
200	0.312	3.83	5.06	3.89	5.04
300	0.468	3.52	5.06	3.58	5.04
400	0.624	3.21	5.05	3.26	5.03
500	0.780	2.90	5.04	2.94	5.02
600	0.936	2.59	5.03	2.62	5.02
700	1.092	2.28	5.02	2.30	5.01
800	1.248	1.98	5.02	1.98	5.00
900	1.404	1.67	5.01	1.66	4.99
1,000	1.560	1.35	5.00	1.34	4.98
1,100	1.716	1.05	4.99	1.03	4.98
1,200	1.872	.74	4.98		4.97
3,000	4.680		4.85		4.83
8,000	12.480		4.46		4.44
18,000	28.080		3.67		3.65
28,000	43.680		2.90		2.87
38,000	59.280		2.12		2.09
48,000	74.880		1.35		1.31
58,000	90.480		.68		.66
59,000	92.040		.62		.62
60,000	93.60		.56		.55

Table 5 TQCM Freq/Volt Converter Output at +50°C Ambient for Input Power Voltage of +28 Vdc \pm 4V. Sensor Beat Freq at Zero Loading 2KHz

Sensor Beat Freq Change	Mass Loading Change	Hi-Sens. Out. No. 1	Lo-Sens. Out. No. 1	Hi-Sens. Out. No. 2	Lo-Sens. Out. No. 2
(Hz)	(g/cm ² \times 10 ⁻⁶)	(V)	(V)	(V)	(V)
-200	0.312	5.16	5.12	4.96	4.84
-150	0.234	5.01	5.11	4.95	5.12
-100	0.156	4.86	5.11	4.97	4.95
-50	0.078	4.71	5.10	4.81	4.99
0	0	4.56	5.10	4.66	5.08
100	0.156	4.26	5.09	4.36	5.07
200	0.312	3.96	5.09	4.05	5.06
300	0.468	3.65	5.08	3.73	5.06
400	0.624	3.35	5.07	3.42	5.05
500	0.780	3.04	5.06	3.10	5.04
600	0.936	2.73	5.05	2.79	5.04
700	1.092	2.43	5.04	2.48	5.03
800	1.248	2.12	5.03	2.16	5.02
900	1.404	1.81	5.03	1.85	5.01
1,000	1.560	1.51	5.02	1.54	5.00
1,100	1.716	1.21	5.01	1.22	4.99
1,200	1.872	.90	5.01	.91	4.99
3,000	4.680		4.87		4.85
8,000	12.480		4.47		4.45
18,000	28.080		3.69		3.67
28,000	43.680		2.91		2.88
38,000	59.280		2.13		2.10
48,000	74.880		1.35		1.32
58,000	90.480		.67		.67
59,000	92.040		.61		.61
60,000	93.60		.54		.54

Table 6 TQCM Temp Outputs for Different Input Power Voltages at 0°C Ambient

Temp (°C)	+32 Vdc		+28 Vdc		+24 Vdc	
	Temp Output #1	Temp Output #2	Temp Output #1	Temp Output #2	Temp Output #1	Temp Output #2
-110	1.00	1.03	1.00	1.03	1.00	1.03
-100	1.20	1.23	1.20	1.23	1.20	1.22
- 73	1.72	1.75	1.72	1.75	1.72	1.75
- 23	2.67	2.70	2.68	2.70	2.67	2.70
0	3.11	3.13	3.11	3.13	3.11	3.13
+ 27	3.61	3.64	3.61	3.64	3.61	3.64
+ 52	4.08	4.10	4.08	4.10	4.08	4.10
+100	4.96	4.98	4.96	4.98	4.96	4.98
+110	5.14	5.17	5.14	5.17	5.14	5.17

Table 7 TQCM Temp Outputs for Different Input Power Voltages at +20°C Ambient

Temp (°C)	+32 Vdc		+28 Vdc		+24 Vdc	
	Temp Output #1 (V)	Temp Output #2 (V)	Temp Output #1 (V)	Temp Output #2 (V)	Temp Output #1 (V)	Temp Output #2 (V)
-110	1.00	1.03	1.00	1.03	1.00	1.03
-100	1.20	1.23	1.20	1.23	1.20	1.23
⁴¹ - 73	1.72	1.75	1.72	1.75	1.72	1.75
- 23	2.68	2.70	2.68	2.70	2.68	2.70
0	3.11	3.13	3.11	3.13	3.11	3.13
+ 27	3.62	3.63	3.62	3.64	3.62	3.64
+ 52	4.08	4.10	4.08	4.10	4.08	4.10
+100	4.96	4.98	4.96	4.98	4.96	4.98
+110	5.15	5.17	5.15	5.16	5.15	5.17

Table 8 TQCM Temp Outputs for Different Input Power Voltages at +30°C Ambient

Temp (°C)	+32 Vdc		+28 Vdc		+24 Vdc	
	Temp Output #1 (V)	Temp Output #2 (V)	Temp Output #1 (V)	Temp Output #2 (V)	Temp Output #1 (V)	Temp Output #2 (V)
-110	1.00	1.03	1.00	1.03	1.00	1.03
-100	1.20	1.23	1.20	1.23	1.20	1.23
-73	1.72	1.75	1.72	1.75	1.72	1.75
-23	2.68	2.70	2.68	2.70	2.68	2.70
0	3.11	3.14	3.11	3.14	3.11	3.14
+27	3.62	3.64	3.62	3.64	3.62	3.64
+52	4.08	4.10	4.08	4.10	4.08	4.10
+100	4.97	4.99	4.97	4.99	4.97	4.99
+110	5.15	5.17	5.15	5.17	5.15	5.17

Table 9 TQCM Temp Outputs for Different Input Power Voltages at +50°C Ambient

Temp (°C)	+32 Vdc		+28 Vdc		+24 Vdc	
	Temp Output #1 (mV)	Temp Output #2 (mV)	Temp Output #1 (mV)	Temp Output #2 (mV)	Temp Output #1 (mV)	Temp Output #2 (mV)
-110	1.01	1.03	1.01	1.03	1.01	1.03
-100	1.20	1.23	1.20	1.23	1.20	1.23
43	1.73	1.75	1.73	1.75	1.73	1.75
- 23	2.68	2.70	2.68	2.70	2.68	2.70
0	3.12	3.13	3.11	3.13	3.12	3.13
+ 27	3.62	3.64	3.62	3.63	3.62	3.64
+ 52	4.09	4.10	4.09	4.10	4.09	4.10
+100	4.97	4.98	4.97	4.98	4.97	4.98
+110	5.15	5.16	5.15	5.16	5.15	5.16

Table 10 TQCM Commanded and Operating Temp for Different Input Voltages and Ambient Temperatures

Command Temp (°C)	+32 Vdc		0°C		+28 Vdc		+20°C		+30°C		+50°C	
	TQCM No. 1 (°C)	TQCM No. 2 (°C)										
-60	-58.8	-58.9	-58.9	-58.9	-58.9	-59.1	-59.1	-59.2	-59.2	-59.2	-59.3	-59.2
-30	-31.7	-31.4	-31.4	-31.4	-31.4	-31.5	-31.5	-31.5	-31.5	-31.6	-31.7	-31.4
0	-0.6	-0.7	-0.7	-0.7	-0.7	-0.9	-0.9	-0.9	-0.9	-0.9	-0.9	-0.9
+30	+30.3	+30.0	+30.1	+30.1	+29.8	+29.9	+29.9	+29.9	+29.9	+29.9	+29.9	+29.9
+100	+102.1	+101.7	+101.9	+101.9	+101.6	+101.7	+101.7	+101.7	+101.7	+101.5	+101.5	+101.7
<hr/>												
-60	-58.6	-58.6	-58.6	-58.6	-58.6	-58.6	-58.6	-58.6	-58.6	-58.6	-58.9	-58.9
-30	-31.2	-31.2	-31.2	-31.2	-31.2	-31.4	-31.4	-31.4	-31.4	-31.4	-31.6	-31.6
0	-0.7	-0.7	-0.7	-0.7	-0.7	-0.7	-0.7	-0.7	-0.7	-0.7	-0.9	-0.9
+30	+30.1	+30.2	+30.0	+30.0	+30.1	+30.1	+30.1	+30.1	+30.1	+30.1	+30.0	+30.0
+100	+101.2	+102.0	+101.5	+101.5	+101.8	+101.8	+101.8	+101.8	+101.8	+101.5	+101.5	+101.5
<hr/>												
-60	-58.9	-58.9	-58.9	-58.9	-58.9	-58.9	-58.9	-58.9	-58.9	-58.9	-59.1	-59.1
-30	-31.3	-31.2	-31.2	-31.2	-31.2	-31.4	-31.4	-31.4	-31.4	-31.4	-31.6	-31.6
0	-0.6	-0.6	-0.6	-0.6	-0.6	-0.7	-0.7	-0.7	-0.7	-0.7	-0.9	-0.9
+30	+30.1	+30.1	+30.0	+30.0	+30.0	+30.0	+30.0	+30.0	+30.0	+30.0	+29.9	+29.9
+100	+101.8	+101.8	+101.7	+101.7	+101.7	+101.7	+101.7	+101.7	+101.7	+101.5	+101.5	+101.5
<hr/>												
-60	-59.0	-58.7	-59.2	-58.9	-58.9	-58.9	-58.9	-58.9	-58.9	-58.9	-59.3	-59.2
-30	-31.4	-31.2	-31.4	-31.2	-31.2	-31.2	-31.2	-31.2	-31.2	-31.2	-31.7	-31.4
0	-0.7	-0.5	-0.5	-0.9	-0.7	-0.7	-0.7	-0.7	-0.7	-0.7	-1.1	-0.9
+30	+30.0	+30.3	+29.8	+30.1	+30.1	+30.1	+30.1	+30.1	+30.1	+30.1	+29.7	+29.9
+100	+101.8	+102.3	+101.7	+101.7	+101.7	+101.7	+101.7	+101.7	+101.7	+101.5	+101.5	+101.7

Table 11 Power Supply Calibration at 0°C Ambient

TQCM Electronics ON and Heaters OFF					
Volts In (Vdc)	Current In (mA)	Power In		+5V Monitor (Vdc)	
		(W)	+5V Monitor (Vdc)	(Vdc)	+15V Monitor (Vdc)
24	91.0	2.184	2.58	2.22	
28	82.0	2.296	2.57	2.22	
32	72.5	2.304	2.57	2.22	

TQCM Electronics and Heaters ON					
Volts In (Vdc)	Electronics & Heater 1 (W)	Electronics & Heater 2 (W)		Electronics & Heaters 1 & 2 (W)	
		(W)	(Vdc)	(W)	(Vdc)
24	3.528	3.648	5.016	5.012	2.59 2.22
28	3.696	3.836	5.012	4.960	2.58 2.22
32	3.712	3.808	4.960		2.52 2.22

Note: Test points for monitoring +5V and +15V supplies are in series with voltage dividers to protect supplies from accidental grounding and possible burn out. Hence, values given indicate supplies are properly functioning.

Table 12 Power Supply Calibration at +20°C Ambient

TQCM Electronics ON and Heaters OFF				TQCM Electronics and Heaters ON			
Volts In (Vdc)	Current In (mA)	Power In (W)		Power In (W)		Monitors Max Pwr 5V 15V (Vdc) (Vdc)	
		+5V Monitor		+15V Monitor		Electronics & Heaters 1 & 2 (W)	
24	87.0	2.088		2.60		2.22	
28	76.5		2.142		2.59		2.22
32	70.0		2.240		2.59		2.22

Table 13 Power Supply Calibration at +30°C Ambient

TQCM Electronics ON and Heaters OFF				TQCM Electronics and Heaters ON			
Volts In (Vdc)	Current In (mA)	Power In		Power In		Monitors Max Pwr	
		(W)	(Vdc)	(W)	(Vdc)	5V	15V
24	87.0	2.088	2.60			2.60	2.22
28	77.0	2.156	2.59			2.59	2.22
32	70.0	2.240	2.59			2.59	2.22

Table 14 Power Supply Calibration at +50 °C Ambient

TQCM Electronics ON and Heater OFF					
Volts In (Vdc)	Current In (mA)	Power In		+5V Monitor (Vdc)	+15V Monitor (Vdc)
		(W)	(W)		
24	86.0	2.064	2.064	2.61	2.22
28	76.0	2.128	2.128	2.61	2.23
32	70.0	2.240	2.240	2.60	2.23

TQCM Electronics and Heaters ON					
Volts In (Vdc)	Electronics & Heater 1 (W)	Electronics & Heater 2 (W)		Electronics & Heaters 1 & 2 (W)	Monitors Max Pwr 5V (Vdc) (Vdc)
24	3.552	3.600	3.600	5.040	2.61 2.22
29	3.724	3.752	3.752	5.040	2.62 2.23
32	3.744	3.776	3.776	4.960	2.54 2.23




Figure 31 TQCM 15-MHz Sensor Calibration




Figure 32 TQCM Head H-1 High-Sensitivity Analog Mass Calibration
50




Figure 33 TQCM Head H-1 Los-Sensitivity Analog Mass Calibration




Figure 34 TQCM Head H-1 Temp Calibration




Figure 35 TQCM Head H-2 High-Sensitivity Analog Mass Calibration




Figure 36 TQCM Head H-2 Low-Sensitivity Analog Mass Calibration




Figure 37 TQCM Head H-2 Temp Calibration
55

too small to plot. If these variations are to be observed, tabulated data must be used.

6.0 Command Logic

The TQCM System command logic is shown in Table 15.

When the TQCM is commanded to free run, the decoder relay (Figure 28) places 100.8 ohms (R_8) into the temperature control circuit. The nulling temperature for this resistance is -164.6°C or slightly less than the minimum calculated TQCM operating temperature. The reason this resistance value was chosen was to minimize power dissipation during free run but provide a null temperature commensurate to the minimum TQCM operating temperature.

Table 15 TQCM System Serial Command Logic

<u>Serial Bits</u>					<u>Temperature Command</u>
1-18	19	20	21	22	
X	0	0	0	0	Free Run (min temp)
X	1	0	0	0	-60°C
X	0	1	0	0	-30°C
X	1	1	0	0	0°C
X	0	0	1	1	$+30^{\circ}\text{C}$
X	1	0	1	0	$+100^{\circ}\text{C}$

REFERENCES

1. McKeown, D., Sonnenschein, G. and Fox, M.G., Cryogenic Quartz Crystal Microbalance, Final Report, FAR-D-001-76, Faraday Laboratories Inc., Prepared for NASA, MSFC, Jan. (1976).
2. McKeown, D., Sonnenschein, G. and Fox, M.G., "CQCM", 8th Space Simulation Conference, NASA SP-379, p. 343, Nov. (1975).

APPENDIX

TQCM SYSTEM

MECHANICAL DESIGN




Figure 38




Figure 39





Figure 40






Figure 42




Figure 43




Figure 44




Figure 45




Figure 46




Figure 47




Figure 48




Figure 49




Figure 50




Figure 51





Figure 52



73

◀ Figure 53




Figure 54




Figure 55




Figure 56

REVSIONS		DESCRIPTION		DATE	APPROVED																																																												
ZONE	LTR																																																																
<u>WASHER</u>																																																																	
<p>OD AND ID SAME AS SPACER</p>																																																																	
<p>OD <u>$0.250'$</u> ID <u>$0.113'$</u> #33 DRILL <u>$0.29'$</u></p> <p>L #1 SPACER <u>$0.560'$</u> 12 PC REQ.</p> <p>#2 SPACER <u>$0.660'$</u> 4 PC REQ.</p> <p>MAT'L - EPOXY FIBRE GLASS, G-10</p>																																																																	
<p>DIMENSIONS INCHES CENTIMETERS</p> <table border="1"> <thead> <tr> <th colspan="2">UNLESS OTHERWISE SPECIFIED</th> <th colspan="4">DIMENSIONS ARE IN INCHES</th> </tr> <tr> <th>THREADS PER MILS</th> <th>7742</th> <th>NUMBER</th> <th>DRAFT</th> <th>ANGLES</th> <th>CHECK</th> </tr> <tr> <th>DIA. & O.L.</th> <th>1.45</th> <th>MEET DIM BEFORE/AFTER FINISH</th> <th>DECIMAL XX</th> <th>XXX ±</th> <th>MECH</th> </tr> <tr> <th>BREAK</th> <th>SHARP EDGES</th> <th>TOLERANCE</th> <th>XX ±</th> <th>±</th> <th>ELEC</th> </tr> </thead> <tbody> <tr> <td>0.135 THRU .125</td> <td>+ .004 - .001</td> <td>DO NOT SCALE DRAWING</td> <td></td> <td></td> <td><i>J. M. J.</i></td> </tr> <tr> <td>.126 THRU .250</td> <td>+ .005 - .001</td> <td>SURFACE ROUGHNESS</td> <td></td> <td></td> <td>TQCM CONTROLLER</td> </tr> <tr> <td>.251 THRU .300</td> <td>+ .006 - .001</td> <td>ENGR</td> <td></td> <td></td> <td>ASSEMBLY PARTS III</td> </tr> <tr> <td>.301 THRU .350</td> <td>+ .007 - .001</td> <td>FINISH</td> <td></td> <td></td> <td></td> </tr> <tr> <td>.351 THRU 1.000</td> <td>+ .010 - .001</td> <td>APPROVAL</td> <td></td> <td></td> <td></td> </tr> <tr> <td>1.001 THRU 2.000</td> <td>+ .012 - .001</td> <td>OTHER APPROVAL</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>						UNLESS OTHERWISE SPECIFIED		DIMENSIONS ARE IN INCHES				THREADS PER MILS	7742	NUMBER	DRAFT	ANGLES	CHECK	DIA. & O.L.	1.45	MEET DIM BEFORE/AFTER FINISH	DECIMAL XX	XXX ±	MECH	BREAK	SHARP EDGES	TOLERANCE	XX ±	±	ELEC	0.135 THRU .125	+ .004 - .001	DO NOT SCALE DRAWING			<i>J. M. J.</i>	.126 THRU .250	+ .005 - .001	SURFACE ROUGHNESS			TQCM CONTROLLER	.251 THRU .300	+ .006 - .001	ENGR			ASSEMBLY PARTS III	.301 THRU .350	+ .007 - .001	FINISH				.351 THRU 1.000	+ .010 - .001	APPROVAL				1.001 THRU 2.000	+ .012 - .001	OTHER APPROVAL			
UNLESS OTHERWISE SPECIFIED		DIMENSIONS ARE IN INCHES																																																															
THREADS PER MILS	7742	NUMBER	DRAFT	ANGLES	CHECK																																																												
DIA. & O.L.	1.45	MEET DIM BEFORE/AFTER FINISH	DECIMAL XX	XXX ±	MECH																																																												
BREAK	SHARP EDGES	TOLERANCE	XX ±	±	ELEC																																																												
0.135 THRU .125	+ .004 - .001	DO NOT SCALE DRAWING			<i>J. M. J.</i>																																																												
.126 THRU .250	+ .005 - .001	SURFACE ROUGHNESS			TQCM CONTROLLER																																																												
.251 THRU .300	+ .006 - .001	ENGR			ASSEMBLY PARTS III																																																												
.301 THRU .350	+ .007 - .001	FINISH																																																															
.351 THRU 1.000	+ .010 - .001	APPROVAL																																																															
1.001 THRU 2.000	+ .012 - .001	OTHER APPROVAL																																																															
<p>NEXT ASY USED ON</p>																																																																	
<p>DASH NO. APPLICATION RELEASED 30 SEPT 76</p>																																																																	
<p>77</p>																																																																	

Figure 57

REVSIONS		DESCRIPTION		DATE	APPROVED																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																										
ZONE	LTR																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																														
MODULE ASSEMBLY ROD																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
<p>D $\frac{0.112}{0.28}$</p> <p>L #1 ROD $\frac{2.700}{6.86}$ 4 PC REQ.</p> <p>#2 ROD $\frac{2.300}{5.84}$ 4 PC REQ.</p>																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
<p style="text-align: right;">DIMENSIONS $\frac{\text{INCHES}}{\text{CENTIMETERS}}$</p> <p>UNLESS OTHERWISE SPECIFIED</p> <table border="1"> <thead> <tr> <th colspan="2">THREADS PER INCH</th> <th colspan="2">DIMENSIONS ARE IN INCHES</th> <th colspan="2">NUMBER</th> </tr> <tr> <th colspan="2">7/16</th> <th colspan="2">.0005 TO .0015</th> <th colspan="2">CRAFT</th> </tr> <tr> <th colspan="2">1/2</th> <th colspan="2">.0005 TO .0015</th> <th colspan="2">CHECK</th> </tr> <tr> <th colspan="2">5/8</th> <th colspan="2">.0005 TO .0015</th> <th colspan="2">ANGLES</th> </tr> <tr> <th colspan="2">3/4</th> <th colspan="2">.0005 TO .0015</th> <th colspan="2">MECH</th> </tr> <tr> <th colspan="2">1</th> <th colspan="2">.0005 TO .0015</th> <th colspan="2">ELEC</th> </tr> </thead> <tbody> <tr> <td colspan="2">THD</td> <td colspan="2">.0005 TO .0015</td> <td colspan="2">NOT SCALE DRAWING</td> </tr> <tr> <td colspan="2">HOLE DIA.</td> <td colspan="2">.0005 TO .0015</td> <td colspan="2">ENGR</td> </tr> <tr> <td colspan="2">TOLERANCE</td> <td colspan="2">.0005 TO .0015</td> <td colspan="2">SURFACE ROUGHNESS</td> </tr> <tr> <td colspan="2">.015 THRU .025</td> <td colspan="2">+.004 -.001</td> <td colspan="2">.001" PER ASA 8A.1</td> </tr> <tr> <td colspan="2">.025 THRU .030</td> <td colspan="2">+.005 -.002</td> <td colspan="2">+.005 -.002</td> </tr> <tr> <td colspan="2">.030 THRU .031</td> <td colspan="2">+.006 -.003</td> <td colspan="2">+.006 -.003</td> </tr> <tr> <td colspan="2">.031 THRU .032</td> <td colspan="2">+.007 -.004</td> <td colspan="2">+.007 -.004</td> </tr> <tr> <td colspan="2">.032 THRU .033</td> <td colspan="2">+.008 -.005</td> <td colspan="2">+.008 -.005</td> </tr> <tr> <td colspan="2">.033 THRU .034</td> <td colspan="2">+.009 -.006</td> <td colspan="2">+.009 -.006</td> </tr> <tr> <td colspan="2">.034 THRU .035</td> <td colspan="2">+.010 -.007</td> <td colspan="2">+.010 -.007</td> </tr> <tr> <td colspan="2">.035 THRU .036</td> <td colspan="2">+.011 -.008</td> <td colspan="2">+.011 -.008</td> </tr> <tr> <td colspan="2">.036 THRU .037</td> <td colspan="2">+.012 -.009</td> <td colspan="2">+.012 -.009</td> </tr> <tr> <td colspan="2">.037 THRU .038</td> <td colspan="2">+.013 -.010</td> <td colspan="2">+.013 -.010</td> </tr> <tr> <td colspan="2">.038 THRU .039</td> <td colspan="2">+.014 -.011</td> <td colspan="2">+.014 -.011</td> </tr> <tr> <td colspan="2">.039 THRU .040</td> <td colspan="2">+.015 -.012</td> <td colspan="2">+.015 -.012</td> </tr> <tr> <td colspan="2">.040 THRU .041</td> <td colspan="2">+.016 -.013</td> <td colspan="2">+.016 -.013</td> </tr> <tr> <td colspan="2">.041 THRU .042</td> <td colspan="2">+.017 -.014</td> <td colspan="2">+.017 -.014</td> </tr> <tr> <td colspan="2">.042 THRU .043</td> <td colspan="2">+.018 -.015</td> <td colspan="2">+.018 -.015</td> </tr> <tr> <td colspan="2">.043 THRU .044</td> <td colspan="2">+.019 -.016</td> <td colspan="2">+.019 -.016</td> </tr> <tr> <td colspan="2">.044 THRU .045</td> <td colspan="2">+.020 -.017</td> <td colspan="2">+.020 -.017</td> </tr> <tr> <td colspan="2">.045 THRU .046</td> <td colspan="2">+.021 -.018</td> <td colspan="2">+.021 -.018</td> </tr> <tr> <td colspan="2">.046 THRU .047</td> <td colspan="2">+.022 -.019</td> <td colspan="2">+.022 -.019</td> </tr> <tr> <td colspan="2">.047 THRU .048</td> <td colspan="2">+.023 -.020</td> <td colspan="2">+.023 -.020</td> </tr> <tr> <td colspan="2">.048 THRU .049</td> <td colspan="2">+.024 -.021</td> <td colspan="2">+.024 -.021</td> </tr> <tr> <td colspan="2">.049 THRU .050</td> <td colspan="2">+.025 -.022</td> <td colspan="2">+.025 -.022</td> </tr> <tr> <td colspan="2">.050 THRU .051</td> <td colspan="2">+.026 -.023</td> <td colspan="2">+.026 -.023</td> </tr> <tr> <td colspan="2">.051 THRU .052</td> <td colspan="2">+.027 -.024</td> <td colspan="2">+.027 -.024</td> </tr> <tr> <td colspan="2">.052 THRU .053</td> <td colspan="2">+.028 -.025</td> <td colspan="2">+.028 -.025</td> </tr> <tr> <td colspan="2">.053 THRU .054</td> <td colspan="2">+.029 -.026</td> <td colspan="2">+.029 -.026</td> </tr> <tr> <td colspan="2">.054 THRU .055</td> <td colspan="2">+.030 -.027</td> <td colspan="2">+.030 -.027</td> </tr> <tr> <td colspan="2">.055 THRU .056</td> <td colspan="2">+.031 -.028</td> <td colspan="2">+.031 -.028</td> </tr> <tr> <td colspan="2">.056 THRU .057</td> <td colspan="2">+.032 -.029</td> <td colspan="2">+.032 -.029</td> </tr> <tr> <td colspan="2">.057 THRU .058</td> <td colspan="2">+.033 -.030</td> <td colspan="2">+.033 -.030</td> </tr> <tr> <td colspan="2">.058 THRU .059</td> <td colspan="2">+.034 -.031</td> <td colspan="2">+.034 -.031</td> </tr> <tr> <td colspan="2">.059 THRU .060</td> <td colspan="2">+.035 -.032</td> <td colspan="2">+.035 -.032</td> </tr> <tr> <td colspan="2">.060 THRU .061</td> <td colspan="2">+.036 -.033</td> <td colspan="2">+.036 -.033</td> </tr> <tr> <td colspan="2">.061 THRU .062</td> <td colspan="2">+.037 -.034</td> <td colspan="2">+.037 -.034</td> </tr> <tr> <td colspan="2">.062 THRU .063</td> <td colspan="2">+.038 -.035</td> <td colspan="2">+.038 -.035</td> </tr> <tr> <td colspan="2">.063 THRU .064</td> <td colspan="2">+.039 -.036</td> <td colspan="2">+.039 -.036</td> </tr> <tr> <td colspan="2">.064 THRU .065</td> <td colspan="2">+.040 -.037</td> <td colspan="2">+.040 -.037</td> </tr> <tr> <td colspan="2">.065 THRU .066</td> <td colspan="2">+.041 -.038</td> <td colspan="2">+.041 -.038</td> </tr> <tr> <td colspan="2">.066 THRU .067</td> <td colspan="2">+.042 -.039</td> <td colspan="2">+.042 -.039</td> </tr> <tr> <td colspan="2">.067 THRU .068</td> <td colspan="2">+.043 -.040</td> <td colspan="2">+.043 -.040</td> </tr> <tr> <td colspan="2">.068 THRU .069</td> <td colspan="2">+.044 -.041</td> <td colspan="2">+.044 -.041</td> </tr> <tr> <td colspan="2">.069 THRU .070</td> <td colspan="2">+.045 -.042</td> <td colspan="2">+.045 -.042</td> </tr> <tr> <td colspan="2">.070 THRU .071</td> <td colspan="2">+.046 -.043</td> <td colspan="2">+.046 -.043</td> </tr> <tr> <td colspan="2">.071 THRU .072</td> <td colspan="2">+.047 -.044</td> <td colspan="2">+.047 -.044</td> </tr> <tr> <td colspan="2">.072 THRU .073</td> <td colspan="2">+.048 -.045</td> <td colspan="2">+.048 -.045</td> </tr> <tr> <td colspan="2">.073 THRU .074</td> <td colspan="2">+.049 -.046</td> <td colspan="2">+.049 -.046</td> </tr> <tr> <td colspan="2">.074 THRU .075</td> <td colspan="2">+.050 -.047</td> <td colspan="2">+.050 -.047</td> </tr> <tr> <td colspan="2">.075 THRU .076</td> <td colspan="2">+.051 -.048</td> <td colspan="2">+.051 -.048</td> </tr> <tr> <td colspan="2">.076 THRU .077</td> <td colspan="2">+.052 -.049</td> <td colspan="2">+.052 -.049</td> </tr> <tr> <td colspan="2">.077 THRU .078</td> <td colspan="2">+.053 -.050</td> <td colspan="2">+.053 -.050</td> </tr> <tr> <td colspan="2">.078 THRU .079</td> <td colspan="2">+.054 -.051</td> <td colspan="2">+.054 -.051</td> </tr> <tr> <td colspan="2">.079 THRU .080</td> <td colspan="2">+.055 -.052</td> <td colspan="2">+.055 -.052</td> </tr> <tr> <td colspan="2">.080 THRU .081</td> <td colspan="2">+.056 -.053</td> <td colspan="2">+.056 -.053</td> </tr> <tr> <td colspan="2">.081 THRU .082</td> <td colspan="2">+.057 -.054</td> <td colspan="2">+.057 -.054</td> </tr> <tr> <td colspan="2">.082 THRU .083</td> <td colspan="2">+.058 -.055</td> <td colspan="2">+.058 -.055</td> </tr> <tr> <td colspan="2">.083 THRU .084</td> <td colspan="2">+.059 -.056</td> <td colspan="2">+.059 -.056</td> </tr> <tr> <td colspan="2">.084 THRU .085</td> <td colspan="2">+.060 -.057</td> <td colspan="2">+.060 -.057</td> </tr> <tr> <td colspan="2">.085 THRU .086</td> <td colspan="2">+.061 -.058</td> <td colspan="2">+.061 -.058</td> </tr> <tr> <td colspan="2">.086 THRU .087</td> <td colspan="2">+.062 -.059</td> <td colspan="2">+.062 -.059</td> </tr> <tr> <td colspan="2">.087 THRU .088</td> <td colspan="2">+.063 -.060</td> <td colspan="2">+.063 -.060</td> </tr> <tr> <td colspan="2">.088 THRU .089</td> <td colspan="2">+.064 -.061</td> <td colspan="2">+.064 -.061</td> </tr> <tr> <td colspan="2">.089 THRU .090</td> <td colspan="2">+.065 -.062</td> <td colspan="2">+.065 -.062</td> </tr> <tr> <td colspan="2">.090 THRU .091</td> <td colspan="2">+.066 -.063</td> <td colspan="2">+.066 -.063</td> </tr> <tr> <td colspan="2">.091 THRU .092</td> <td colspan="2">+.067 -.064</td> <td colspan="2">+.067 -.064</td> </tr> <tr> <td colspan="2">.092 THRU .093</td> <td colspan="2">+.068 -.065</td> <td colspan="2">+.068 -.065</td> </tr> <tr> <td colspan="2">.093 THRU .094</td> <td colspan="2">+.069 -.066</td> <td colspan="2">+.069 -.066</td> </tr> <tr> <td colspan="2">.094 THRU .095</td> <td colspan="2">+.070 -.067</td> <td colspan="2">+.070 -.067</td> </tr> <tr> <td colspan="2">.095 THRU .096</td> <td colspan="2">+.071 -.068</td> <td colspan="2">+.071 -.068</td> </tr> <tr> <td colspan="2">.096 THRU .097</td> <td colspan="2">+.072 -.069</td> <td colspan="2">+.072 -.069</td> </tr> <tr> <td colspan="2">.097 THRU .098</td> <td colspan="2">+.073 -.070</td> <td colspan="2">+.073 -.070</td> </tr> <tr> <td colspan="2">.098 THRU .099</td> <td colspan="2">+.074 -.071</td> <td colspan="2">+.074 -.071</td> </tr> <tr> <td colspan="2">.099 THRU .100</td> <td colspan="2">+.075 -.072</td> <td colspan="2">+.075 -.072</td> </tr> <tr> <td colspan="2">.100 THRU .101</td> <td colspan="2">+.076 -.073</td> <td colspan="2">+.076 -.073</td> </tr> <tr> <td colspan="2">.101 THRU .102</td> <td colspan="2">+.077 -.074</td> <td colspan="2">+.077 -.074</td> </tr> <tr> <td colspan="2">.102 THRU .103</td> <td colspan="2">+.078 -.075</td> <td colspan="2">+.078 -.075</td> </tr> <tr> <td colspan="2">.103 THRU .104</td> <td colspan="2">+.079 -.076</td> <td colspan="2">+.079 -.076</td> </tr> <tr> <td colspan="2">.104 THRU .105</td> <td colspan="2">+.080 -.077</td> <td colspan="2">+.080 -.077</td> </tr> <tr> <td colspan="2">.105 THRU .106</td> <td colspan="2">+.081 -.078</td> <td colspan="2">+.081 -.078</td> </tr> <tr> <td colspan="2">.106 THRU .107</td> <td colspan="2">+.082 -.079</td> <td colspan="2">+.082 -.079</td> </tr> <tr> <td colspan="2">.107 THRU .108</td> <td colspan="2">+.083 -.080</td> <td colspan="2">+.083 -.080</td> </tr> <tr> <td colspan="2">.108 THRU .109</td> <td colspan="2">+.084 -.081</td> <td colspan="2">+.084 -.081</td> </tr> <tr> <td colspan="2">.109 THRU .110</td> <td colspan="2">+.085 -.082</td> <td colspan="2">+.085 -.082</td> </tr> <tr> <td colspan="2">.110 THRU .111</td> <td colspan="2">+.086 -.083</td> <td colspan="2">+.086 -.083</td> </tr> <tr> <td colspan="2">.111 THRU .112</td> <td colspan="2">+.087 -.084</td> <td colspan="2">+.087 -.084</td> </tr> <tr> <td colspan="2">.112 THRU .113</td> <td colspan="2">+.088 -.085</td> <td colspan="2">+.088 -.085</td> </tr> <tr> <td colspan="2">.113 THRU .114</td> <td colspan="2">+.089 -.086</td> <td colspan="2">+.089 -.086</td> </tr> <tr> <td colspan="2">.114 THRU .115</td> <td colspan="2">+.090 -.087</td> <td colspan="2">+.090 -.087</td> </tr> <tr> <td colspan="2">.115 THRU .116</td> <td colspan="2">+.091 -.088</td> <td colspan="2">+.091 -.088</td> </tr> <tr> <td colspan="2">.116 THRU .117</td> <td colspan="2">+.092 -.089</td> <td colspan="2">+.092 -.089</td> </tr> <tr> <td colspan="2">.117 THRU .118</td> <td colspan="2">+.093 -.090</td> <td colspan="2">+.093 -.090</td> </tr> <tr> <td colspan="2">.118 THRU .119</td> <td colspan="2">+.094 -.091</td> <td colspan="2">+.094 -.091</td> </tr> <tr> <td colspan="2">.119 THRU .120</td> <td colspan="2">+.095 -.092</td> <td colspan="2">+.095 -.092</td> </tr> <tr> <td colspan="2">.120 THRU .121</td> <td colspan="2">+.096 -.093</td> <td colspan="2">+.096 -.093</td> </tr> <tr> <td colspan="2">.121 THRU .122</td> <td colspan="2">+.097 -.094</td> <td colspan="2">+.097 -.094</td> </tr> <tr> <td colspan="2">.122 THRU .123</td> <td colspan="2">+.098 -.095</td> <td colspan="2">+.098 -.095</td> </tr> <tr> <td colspan="2">.123 THRU .124</td> <td colspan="2">+.099 -.096</td> <td colspan="2">+.099 -.096</td> </tr> <tr> <td colspan="2">.124 THRU .125</td> <td colspan="2">+.100 -.097</td> <td colspan="2">+.100 -.097</td> </tr> <tr> <td colspan="2">.125 THRU .126</td> <td colspan="2">+.101 -.098</td> <td colspan="2">+.101 -.098</td> </tr> <tr> <td colspan="2">.126 THRU .127</td> <td colspan="2">+.102 -.099</td> <td colspan="2">+.102 -.099</td> </tr> <tr> <td colspan="2">.127 THRU .128</td> <td colspan="2">+.103 -.100</td> <td colspan="2">+.103 -.100</td> </tr> <tr> <td colspan="2">.128 THRU .129</td> <td colspan="2">+.104 -.101</td> <td colspan="2">+.104 -.101</td> </tr> <tr> <td colspan="2">.129 THRU .130</td> <td colspan="2">+.105 -.102</td> <td colspan="2">+.105 -.102</td> </tr> <tr> <td colspan="2">.130 THRU .131</td> <td colspan="2">+.106 -.103</td> <td colspan="2">+.106 -.103</td> </tr> <tr> <td colspan="2">.131 THRU .132</td> <td colspan="2">+.107 -.104</td> <td colspan="2">+.107 -.104</td> </tr> <tr> <td colspan="2">.132 THRU .133</td> <td colspan="2">+.108 -.105</td> <td colspan="2">+.108 -.105</td> </tr> <tr> <td colspan="2">.133 THRU .134</td> <td colspan="2">+.109 -.106</td> <td colspan="2">+.109 -.106</td> </tr> <tr> <td colspan="2">.134 THRU .135</td> <td colspan="2">+.110 -.107</td> <td colspan="2">+.110 -.107</td> </tr> <tr> <td colspan="2">.135 THRU .136</td> <td colspan="2">+.111 -.108</td> <td colspan="2">+.111 -.108</td> </tr> <tr> <td colspan="2">.136 THRU .137</td> <td colspan="2">+.112 -.109</td> <td colspan="2">+.112 -.109</td> </tr> <tr> <td colspan="2">.137 THRU .138</td> <td colspan="2">+.113 -.110</td> <td colspan="2">+.113 -.110</td> </tr> <tr> <td colspan="2">.138 THRU .139</td> <td colspan="2">+.114 -.111</td> <td colspan="2">+.114 -.111</td> </tr> <tr> <td colspan="2">.139 THRU .140</td> <td colspan="2">+.115 -.112</td> <td colspan="2">+.115 -.112</td> </tr> <tr> <td colspan="2">.140 THRU .141</td> <td colspan="2">+.116 -.113</td> <td colspan="2">+.116 -.113</td> </tr> <tr> <td colspan="2">.141 THRU .142</td> <td colspan="2">+.117 -.114</td> <td colspan="2">+.117 -.114</td> </tr> <tr> <td colspan="2">.142 THRU .143</td> <td colspan="2">+.118 -.115</td> <td colspan="2">+.118 -.115</td> </tr> <tr> <td colspan="2">.143 THRU .144</td> <td colspan="2">+.119 -.116</td> <td colspan="2">+.119 -.116</td> </tr> <tr> <td colspan="2">.144 THRU .145</td> <td colspan="2">+.120 -.117</td> <td colspan="2">+.120 -.117</td> </tr> <tr> <td colspan="2">.145 THRU .146</td> <td colspan="2">+.121 -.118</td> <td colspan="2">+.121 -.118</td> </tr> <tr> <td colspan="2">.146 THRU .147</td> <td colspan="2">+.122 -.119</td> <td colspan="2">+.122 -.119</td> </tr> <tr> <td colspan="2">.147 THRU .148</td> <td colspan="2">+.123 -.120</td> <td colspan="2">+.123 -.120</td> </tr> <tr> <td colspan="2">.148 THRU .149</td> <td colspan="2">+.124 -.121</td> <td colspan="2">+.124 -.121</td> </tr> <tr> <td colspan="2">.149 THRU .150</td> <td colspan="2">+.125 -.122</td> <td colspan="2">+.125 -.122</td> </tr> <tr> <td colspan="2">.150 THRU .151</td> <td colspan="2">+.126 -.123</td> <td colspan="2">+.126 -.123</td> </tr> <tr> <td colspan="2">.151 THRU .152</td> <td colspan="2">+.127 -.124</td> <td colspan="2">+.127 -.124</td> </tr> <tr> <td colspan="2">.152 THRU .153</td> <td colspan="2">+.128 -.125</td> <td colspan="2">+.128 -.125</td> </tr> <tr> <td colspan="2">.153 THRU .154</td> <td colspan="2">+.129 -.126</td> <td colspan="2">+.129 -.126</td> </tr> <tr> <td colspan="2">.154 THRU .155</td> <td colspan="2">+.130 -.127</td> <td colspan="2">+.130 -.127</td> </tr> <tr> <td colspan="2">.155 THRU .156</td> <td colspan="2">+.131 -.128</td> <td colspan="2">+.131 -.128</td> </tr> <tr> <td colspan="2">.156 THRU .157</td> <td colspan="2">+.132 -.129</td> <td colspan="2">+.132 -.129</td> </tr> <tr> <td colspan="2">.157 THRU .158</td> <td colspan="2">+.133 -.130</td> <td colspan="2">+.133 -.130</td> </tr> <tr> <td colspan="2">.158 THRU .159</td> <td colspan="2">+.134 -.131</td> <td colspan="2">+.134 -.131</td> </tr> <tr> <td colspan="2">.159 THRU .160</td> <td colspan="2">+.135 -.132</td> <td colspan="2">+.135 -.132</td> </tr> <tr> <td colspan="2">.160 THRU .161</td> <td colspan="2">+.136 -.133</td> <td colspan="2">+.136 -.133</td> </tr> <tr> <td colspan="2">.161 THRU .162</td> <td colspan="2">+.137 -.134</td> <td colspan="2">+.137 -.134</td> </tr> <tr> <td colspan="2">.162 THRU .163</td> <td colspan="2">+.138 -.135</td> <td colspan="2">+.138 -.135</td> </tr> <tr> <td colspan="2">.163 THRU .164</td> <td colspan="2">+.139 -.136</td> <td colspan="2">+.139 -.136</td> </tr> <tr> <td colspan="2">.164 THRU .165</td> <td colspan="2">+.140 -.137</td> <td colspan="2">+.140 -.137</td> </tr> <tr> <td colspan="2">.165 THRU .166</td> <td colspan="2">+.141 -.138</td> <td colspan="2">+.141 -.138</td> </tr> <tr> <td colspan="2">.166 THRU .167</td> <td colspan="2">+.142 -.139</td> <td colspan="2">+.142 -.139</td> </tr> <tr> <td colspan="2">.167 THRU .168</td> <td colspan="2">+.143 -.140</td> <td colspan="2">+.143 -.140</td> </tr> <tr> <td colspan="2">.168 THRU .169</td> <td colspan="2">+.144 -.141</td> <td colspan="2">+.144 -.141</td> </tr> <tr> <td colspan="2">.169 THRU .170</td> <td colspan="2">+.145 -.142</td> <td colspan="2">+.145 -.142</td> </tr> <tr> <td colspan="2">.170 THRU .171</td> <td colspan="2">+.146 -.143</td> <td colspan="2">+.146 -.143</td> </tr> <tr> <td colspan="2">.171 THRU .172</td> <td colspan="2">+.147 -.144</td> <td colspan="2">+.147 -.144</td> </tr> <tr> <td colspan="2">.172 THRU .173</td> <td colspan="2">+.148 -.145</td> <td colspan="2">+.148 -.145</td> </tr> <tr> <td colspan="2">.173 THRU .174</td> <td colspan="2">+.149 -.146</td> <td colspan="2">+.149 -.146</td> </tr> <tr> <td colspan="2">.174 THRU .175</td> <td colspan="2">+.150 -.147</td> <td colspan="2">+.150 -.147</td> </tr> <tr> <td colspan="2">.175 THRU .176</td> <td colspan="2">+.151 -.148</td> <td colspan="2">+.151 -.148</td> </tr> <tr> <td colspan="2">.176 THRU .177</td> <td colspan="2">+.152 -.149</td> <td colspan="2">+.152 -.149</td> </tr> <tr> <td colspan="2">.177 THRU .178</td> <td colspan="2">+.153 -.150</td> <td colspan="2">+.153 -.150</td> </tr> <tr> <td colspan="2">.178 THRU .179</td> <td colspan="2">+.154 -.151</td> <td colspan="2">+.154 -.151</td> </tr> <tr> <td colspan="2">.179 THRU .180</td> <td colspan="2">+.155 -.152</td> <td colspan="2">+.155 -.152</td> </tr> <tr> <td colspan="2">.180 THRU .181</td> <td colspan="2">+.156 -.153</td> <td colspan="2">+.156 -.153</td> </tr> <tr> <td colspan="2">.181 THRU .182</td> <td colspan="2">+.157 -.154</td> <td colspan="2">+.157 -.154</td> </tr> <tr> <td colspan="2">.182 THRU .183</td> <td colspan="2">+.158 -.155</td> <td colspan="2">+.158 -.155</td> </tr> <tr> <td colspan="2">.183 THRU .184</td> <td colspan="2">+.159 -.156</td> <td colspan="2">+.159 -.156</td> </tr> <tr> <td colspan="2">.184 THRU .185</td> <td colspan="2">+.160 -.157</td> <td colspan="2">+.160 -.157</td> </tr> <tr> <td colspan="2">.185 THRU .186</td> <td colspan="2">+.161 -.158</td> <td colspan="2">+.161 -.158</td> </tr> <tr> <td colspan="2">.186 THRU .187</td> <td colspan="2">+.162 -.159</td> <td colspan="2">+.162 -.159</td> </tr> <tr> <td colspan="2">.187 THRU .188</td> <td colspan="2">+.163 -.160</td> <td colspan="2">+.163 -.160</td> </tr> <tr> <td colspan="2">.188 THRU .189</td> <td colspan="2">+.164 -.161</td> <td colspan="2">+.164 -.161</td> </tr> <tr> <td colspan="2">.189 THRU .190</td> <td colspan="2">+.165 -.162</td> <td colspan="2">+.165 -.162</td> </tr> <tr> <td colspan="2">.190 THRU .191</td> <td colspan="2">+.166 -.163</td> <td colspan="2">+.166 -.163</td> </tr> <tr> <td colspan="2">.191 THRU .192</td> <td colspan="2">+.167 -.164</td> <td colspan="2">+.167 -.164</td> </tr> <tr> <td colspan="2">.192 THRU .193</td> <td colspan="2">+.168 -.165</td> <td colspan="2">+.168 -.165</td> </tr> <tr> <td colspan="2">.193 THRU .194</td> <td colspan="2">+.169 -.166</td> <td colspan="2">+.169 -.166</td> </tr> <tr> <td colspan="2">.194 THRU .195</td> <td colspan="2">+.170 -.167</td> <td colspan="2">+.170 -.167</td> </tr> <tr> <td colspan="2">.195 THRU .196</td> <td colspan="2">+.171 -.168</td> <td colspan="2">+.171 -.168</td> </tr> <tr> <td colspan="2">.196 THRU .197</td> <td colspan="2">+.172 -.169</td> <td colspan="2">+.172 -.169</td> </tr> <tr> <td colspan="2">.197 THRU .198</td> <td colspan="2">+.173 -.170</td> <td colspan="2">+.173 -.170</td> </tr> <tr> <td colspan="2">.198 THRU .199</td> <td colspan="2">+.174 -.171</td> <td colspan="2">+.174 -.171</td> </tr> <tr> <td colspan="2">.199 THRU .200</td> <td colspan="2">+.175 -.172</td> <td colspan="2">+.175 -.172</td> </tr> <tr> <td colspan="2">.200 THRU .201</td> <td colspan="2">+.176 -.173</td> <td colspan="2">+.176 -.173</td> </tr> <tr> <td colspan="2">.201 THRU .202</td> <td colspan="2">+.177 -.174</td> <td colspan="2">+.177 -.174</td> </tr> <tr> <td colspan="2">.202 THRU .203</td> <td colspan="2">+.178 -.175</td> <td colspan="2">+.178 -.175</td> </tr> <tr> <td colspan="2">.203 THRU .204</td> <td colspan="2">+.179 -.176</td> <td colspan="2">+.179 -.176</td> </tr> <tr> <td colspan="2">.204 THRU .205</td> <td colspan="2">+.180 -.177</td> <td colspan="2">+.180 -.177</td> </tr> <tr> <td colspan="2">.205 THRU .206</td> <td colspan="2">+.181 -.178</td> <td colspan="2">+.181 -.178</td> </tr> <tr> <td colspan="2">.206 THRU .207</td> <td colspan="2">+.182 -.179</td> <td colspan="2">+.182 -.179</td> </tr> <tr> <td colspan="2">.207 THRU .208</td> <td colspan="2">+.183 -.180</td> <td colspan="2">+.183 -.180</td> </tr> <tr> <td colspan="2">.208 THRU .209</td> <td colspan="2">+.184 -.181</td> <td colspan="2">+.184 -.181</td> </tr> <tr> <td colspan="2">.209 THRU .210</td> <td colspan="2">+.185 -.182</td> <td colspan="2">+.185 -.182</td> </tr> <tr> <td colspan="2">.210 THRU .211</td> <td colspan="2">+.186 -.183</td> <td colspan="2">+.186 -.183</td> </tr> <tr> <td colspan="2">.211 THRU .212</td> <td colspan="2">+.187 -.184</td> <td colspan="2">+.187 -.184</td> </tr> <tr> <td colspan="2">.212 THRU .213</td> <td colspan="2">+.188 -.185</td> <td colspan="2">+.188 -.185</td> </tr> <tr> <td colspan="2">.213 THRU .214</td> <td colspan="2">+.189 -.186</td> <td colspan="2">+.189 -.186</td> </tr> <tr> <td colspan="2">.214 THRU .215</td> <td colspan="2">+.190 -.187</td> <td colspan="2">+.190 -.187</td> </tr> <tr> <td colspan="2">.215 THRU .216</td> <td colspan="2">+.191 -.188</td> <td colspan="2">+.191 -.188</td> </tr> <tr> <td colspan="2">.216 THRU .217</td> <td colspan="2">+.192 -.189</td> <td colspan="2">+.192 -.189</td> </tr> <tr> <td colspan="2">.217 THRU .218</td> <td colspan="2">+.193 -.190</td> <td colspan="2">+.193 -.190</td> </tr> <tr> <td colspan="2">.218 THRU .219</td> <td colspan="2">+.194 -.191</td> <td colspan="2">+.194 -.191</td> </tr> <tr> <td colspan="2">.219 THRU .220</td> <td colspan="2">+.195 -.192</td> <td colspan="2">+.195 -.192</td> </tr> <tr> <td colspan="2">.220 THRU .221</td> <td colspan="2">+.</td></tr></tbody></table>						THREADS PER INCH		DIMENSIONS ARE IN INCHES		NUMBER		7/16		.0005 TO .0015		CRAFT		1/2		.0005 TO .0015		CHECK		5/8		.0005 TO .0015		ANGLES		3/4		.0005 TO .0015		MECH		1		.0005 TO .0015		ELEC		THD		.0005 TO .0015		NOT SCALE DRAWING		HOLE DIA.		.0005 TO .0015		ENGR		TOLERANCE		.0005 TO .0015		SURFACE ROUGHNESS		.015 THRU .025		+.004 -.001		.001" PER ASA 8A.1		.025 THRU .030		+.005 -.002		+.005 -.002		.030 THRU .031		+.006 -.003		+.006 -.003		.031 THRU .032		+.007 -.004		+.007 -.004		.032 THRU .033		+.008 -.005		+.008 -.005		.033 THRU .034		+.009 -.006		+.009 -.006		.034 THRU .035		+.010 -.007		+.010 -.007		.035 THRU .036		+.011 -.008		+.011 -.008		.036 THRU .037		+.012 -.009		+.012 -.009		.037 THRU .038		+.013 -.010		+.013 -.010		.038 THRU .039		+.014 -.011		+.014 -.011		.039 THRU .040		+.015 -.012		+.015 -.012		.040 THRU .041		+.016 -.013		+.016 -.013		.041 THRU .042		+.017 -.014		+.017 -.014		.042 THRU .043		+.018 -.015		+.018 -.015		.043 THRU .044		+.019 -.016		+.019 -.016		.044 THRU .045		+.020 -.017		+.020 -.017		.045 THRU .046		+.021 -.018		+.021 -.018		.046 THRU .047		+.022 -.019		+.022 -.019		.047 THRU .048		+.023 -.020		+.023 -.020		.048 THRU .049		+.024 -.021		+.024 -.021		.049 THRU .050		+.025 -.022		+.025 -.022		.050 THRU .051		+.026 -.023		+.026 -.023		.051 THRU .052		+.027 -.024		+.027 -.024		.052 THRU .053		+.028 -.025		+.028 -.025		.053 THRU .054		+.029 -.026		+.029 -.026		.054 THRU .055		+.030 -.027		+.030 -.027		.055 THRU .056		+.031 -.028		+.031 -.028		.056 THRU .057		+.032 -.029		+.032 -.029		.057 THRU .058		+.033 -.030		+.033 -.030		.058 THRU .059		+.034 -.031		+.034 -.031		.059 THRU .060		+.035 -.032		+.035 -.032		.060 THRU .061		+.036 -.033		+.036 -.033		.061 THRU .062		+.037 -.034		+.037 -.034		.062 THRU .063		+.038 -.035		+.038 -.035		.063 THRU .064		+.039 -.036		+.039 -.036		.064 THRU .065		+.040 -.037		+.040 -.037		.065 THRU .066		+.041 -.038		+.041 -.038		.066 THRU .067		+.042 -.039		+.042 -.039		.067 THRU .068		+.043 -.040		+.043 -.040		.068 THRU .069		+.044 -.041		+.044 -.041		.069 THRU .070		+.045 -.042		+.045 -.042		.070 THRU .071		+.046 -.043		+.046 -.043		.071 THRU .072		+.047 -.044		+.047 -.044		.072 THRU .073		+.048 -.045		+.048 -.045		.073 THRU .074		+.049 -.046		+.049 -.046		.074 THRU .075		+.050 -.047		+.050 -.047		.075 THRU .076		+.051 -.048		+.051 -.048		.076 THRU .077		+.052 -.049		+.052 -.049		.077 THRU .078		+.053 -.050		+.053 -.050		.078 THRU .079		+.054 -.051		+.054 -.051		.079 THRU .080		+.055 -.052		+.055 -.052		.080 THRU .081		+.056 -.053		+.056 -.053		.081 THRU .082		+.057 -.054		+.057 -.054		.082 THRU .083		+.058 -.055		+.058 -.055		.083 THRU .084		+.059 -.056		+.059 -.056		.084 THRU .085		+.060 -.057		+.060 -.057		.085 THRU .086		+.061 -.058		+.061 -.058		.086 THRU .087		+.062 -.059		+.062 -.059		.087 THRU .088		+.063 -.060		+.063 -.060		.088 THRU .089		+.064 -.061		+.064 -.061		.089 THRU .090		+.065 -.062		+.065 -.062		.090 THRU .091		+.066 -.063		+.066 -.063		.091 THRU .092		+.067 -.064		+.067 -.064		.092 THRU .093		+.068 -.065		+.068 -.065		.093 THRU .094		+.069 -.066		+.069 -.066		.094 THRU .095		+.070 -.067		+.070 -.067		.095 THRU .096		+.071 -.068		+.071 -.068		.096 THRU .097		+.072 -.069		+.072 -.069		.097 THRU .098		+.073 -.070		+.073 -.070		.098 THRU .099		+.074 -.071		+.074 -.071		.099 THRU .100		+.075 -.072		+.075 -.072		.100 THRU .101		+.076 -.073		+.076 -.073		.101 THRU .102		+.077 -.074		+.077 -.074		.102 THRU .103		+.078 -.075		+.078 -.075		.103 THRU .104		+.079 -.076		+.079 -.076		.104 THRU .105		+.080 -.077		+.080 -.077		.105 THRU .106		+.081 -.078		+.081 -.078		.106 THRU .107		+.082 -.079		+.082 -.079		.107 THRU .108		+.083 -.080		+.083 -.080		.108 THRU .109		+.084 -.081		+.084 -.081		.109 THRU .110		+.085 -.082		+.085 -.082		.110 THRU .111		+.086 -.083		+.086 -.083		.111 THRU .112		+.087 -.084		+.087 -.084		.112 THRU .113		+.088 -.085		+.088 -.085		.113 THRU .114		+.089 -.086		+.089 -.086		.114 THRU .115		+.090 -.087		+.090 -.087		.115 THRU .116		+.091 -.088		+.091 -.088		.116 THRU .117		+.092 -.089		+.092 -.089		.117 THRU .118		+.093 -.090		+.093 -.090		.118 THRU .119		+.094 -.091		+.094 -.091		.119 THRU .120		+.095 -.092		+.095 -.092		.120 THRU .121		+.096 -.093		+.096 -.093		.121 THRU .122		+.097 -.094		+.097 -.094		.122 THRU .123		+.098 -.095		+.098 -.095		.123 THRU .124		+.099 -.096		+.099 -.096		.124 THRU .125		+.100 -.097		+.100 -.097		.125 THRU .126		+.101 -.098		+.101 -.098		.126 THRU .127		+.102 -.099		+.102 -.099		.127 THRU .128		+.103 -.100		+.103 -.100		.128 THRU .129		+.104 -.101		+.104 -.101		.129 THRU .130		+.105 -.102		+.105 -.102		.130 THRU .131		+.106 -.103		+.106 -.103		.131 THRU .132		+.107 -.104		+.107 -.104		.132 THRU .133		+.108 -.105		+.108 -.105		.133 THRU .134		+.109 -.106		+.109 -.106		.134 THRU .135		+.110 -.107		+.110 -.107		.135 THRU .136		+.111 -.108		+.111 -.108		.136 THRU .137		+.112 -.109		+.112 -.109		.137 THRU .138		+.113 -.110		+.113 -.110		.138 THRU .139		+.114 -.111		+.114 -.111		.139 THRU .140		+.115 -.112		+.115 -.112		.140 THRU .141		+.116 -.113		+.116 -.113		.141 THRU .142		+.117 -.114		+.117 -.114		.142 THRU .143		+.118 -.115		+.118 -.115		.143 THRU .144		+.119 -.116		+.119 -.116		.144 THRU .145		+.120 -.117		+.120 -.117		.145 THRU .146		+.121 -.118		+.121 -.118		.146 THRU .147		+.122 -.119		+.122 -.119		.147 THRU .148		+.123 -.120		+.123 -.120		.148 THRU .149		+.124 -.121		+.124 -.121		.149 THRU .150		+.125 -.122		+.125 -.122		.150 THRU .151		+.126 -.123		+.126 -.123		.151 THRU .152		+.127 -.124		+.127 -.124		.152 THRU .153		+.128 -.125		+.128 -.125		.153 THRU .154		+.129 -.126		+.129 -.126		.154 THRU .155		+.130 -.127		+.130 -.127		.155 THRU .156		+.131 -.128		+.131 -.128		.156 THRU .157		+.132 -.129		+.132 -.129		.157 THRU .158		+.133 -.130		+.133 -.130		.158 THRU .159		+.134 -.131		+.134 -.131		.159 THRU .160		+.135 -.132		+.135 -.132		.160 THRU .161		+.136 -.133		+.136 -.133		.161 THRU .162		+.137 -.134		+.137 -.134		.162 THRU .163		+.138 -.135		+.138 -.135		.163 THRU .164		+.139 -.136		+.139 -.136		.164 THRU .165		+.140 -.137		+.140 -.137		.165 THRU .166		+.141 -.138		+.141 -.138		.166 THRU .167		+.142 -.139		+.142 -.139		.167 THRU .168		+.143 -.140		+.143 -.140		.168 THRU .169		+.144 -.141		+.144 -.141		.169 THRU .170		+.145 -.142		+.145 -.142		.170 THRU .171		+.146 -.143		+.146 -.143		.171 THRU .172		+.147 -.144		+.147 -.144		.172 THRU .173		+.148 -.145		+.148 -.145		.173 THRU .174		+.149 -.146		+.149 -.146		.174 THRU .175		+.150 -.147		+.150 -.147		.175 THRU .176		+.151 -.148		+.151 -.148		.176 THRU .177		+.152 -.149		+.152 -.149		.177 THRU .178		+.153 -.150		+.153 -.150		.178 THRU .179		+.154 -.151		+.154 -.151		.179 THRU .180		+.155 -.152		+.155 -.152		.180 THRU .181		+.156 -.153		+.156 -.153		.181 THRU .182		+.157 -.154		+.157 -.154		.182 THRU .183		+.158 -.155		+.158 -.155		.183 THRU .184		+.159 -.156		+.159 -.156		.184 THRU .185		+.160 -.157		+.160 -.157		.185 THRU .186		+.161 -.158		+.161 -.158		.186 THRU .187		+.162 -.159		+.162 -.159		.187 THRU .188		+.163 -.160		+.163 -.160		.188 THRU .189		+.164 -.161		+.164 -.161		.189 THRU .190		+.165 -.162		+.165 -.162		.190 THRU .191		+.166 -.163		+.166 -.163		.191 THRU .192		+.167 -.164		+.167 -.164		.192 THRU .193		+.168 -.165		+.168 -.165		.193 THRU .194		+.169 -.166		+.169 -.166		.194 THRU .195		+.170 -.167		+.170 -.167		.195 THRU .196		+.171 -.168		+.171 -.168		.196 THRU .197		+.172 -.169		+.172 -.169		.197 THRU .198		+.173 -.170		+.173 -.170		.198 THRU .199		+.174 -.171		+.174 -.171		.199 THRU .200		+.175 -.172		+.175 -.172		.200 THRU .201		+.176 -.173		+.176 -.173		.201 THRU .202		+.177 -.174		+.177 -.174		.202 THRU .203		+.178 -.175		+.178 -.175		.203 THRU .204		+.179 -.176		+.179 -.176		.204 THRU .205		+.180 -.177		+.180 -.177		.205 THRU .206		+.181 -.178		+.181 -.178		.206 THRU .207		+.182 -.179		+.182 -.179		.207 THRU .208		+.183 -.180		+.183 -.180		.208 THRU .209		+.184 -.181		+.184 -.181		.209 THRU .210		+.185 -.182		+.185 -.182		.210 THRU .211		+.186 -.183		+.186 -.183		.211 THRU .212		+.187 -.184		+.187 -.184		.212 THRU .213		+.188 -.185		+.188 -.185		.213 THRU .214		+.189 -.186		+.189 -.186		.214 THRU .215		+.190 -.187		+.190 -.187		.215 THRU .216		+.191 -.188		+.191 -.188		.216 THRU .217		+.192 -.189		+.192 -.189		.217 THRU .218		+.193 -.190		+.193 -.190		.218 THRU .219		+.194 -.191		+.194 -.191		.219 THRU .220		+.195 -.192		+.195 -.192		.220 THRU .221		+.	
THREADS PER INCH		DIMENSIONS ARE IN INCHES		NUMBER																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
7/16		.0005 TO .0015		CRAFT																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
1/2		.0005 TO .0015		CHECK																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
5/8		.0005 TO .0015		ANGLES																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
3/4		.0005 TO .0015		MECH																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
1		.0005 TO .0015		ELEC																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
THD		.0005 TO .0015		NOT SCALE DRAWING																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
HOLE DIA.		.0005 TO .0015		ENGR																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
TOLERANCE		.0005 TO .0015		SURFACE ROUGHNESS																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.015 THRU .025		+.004 -.001		.001" PER ASA 8A.1																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.025 THRU .030		+.005 -.002		+.005 -.002																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.030 THRU .031		+.006 -.003		+.006 -.003																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.031 THRU .032		+.007 -.004		+.007 -.004																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.032 THRU .033		+.008 -.005		+.008 -.005																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.033 THRU .034		+.009 -.006		+.009 -.006																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.034 THRU .035		+.010 -.007		+.010 -.007																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.035 THRU .036		+.011 -.008		+.011 -.008																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.036 THRU .037		+.012 -.009		+.012 -.009																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.037 THRU .038		+.013 -.010		+.013 -.010																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.038 THRU .039		+.014 -.011		+.014 -.011																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.039 THRU .040		+.015 -.012		+.015 -.012																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.040 THRU .041		+.016 -.013		+.016 -.013																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.041 THRU .042		+.017 -.014		+.017 -.014																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.042 THRU .043		+.018 -.015		+.018 -.015																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.043 THRU .044		+.019 -.016		+.019 -.016																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.044 THRU .045		+.020 -.017		+.020 -.017																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.045 THRU .046		+.021 -.018		+.021 -.018																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.046 THRU .047		+.022 -.019		+.022 -.019																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.047 THRU .048		+.023 -.020		+.023 -.020																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.048 THRU .049		+.024 -.021		+.024 -.021																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.049 THRU .050		+.025 -.022		+.025 -.022																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.050 THRU .051		+.026 -.023		+.026 -.023																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.051 THRU .052		+.027 -.024		+.027 -.024																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.052 THRU .053		+.028 -.025		+.028 -.025																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.053 THRU .054		+.029 -.026		+.029 -.026																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.054 THRU .055		+.030 -.027		+.030 -.027																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.055 THRU .056		+.031 -.028		+.031 -.028																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.056 THRU .057		+.032 -.029		+.032 -.029																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.057 THRU .058		+.033 -.030		+.033 -.030																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.058 THRU .059		+.034 -.031		+.034 -.031																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.059 THRU .060		+.035 -.032		+.035 -.032																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.060 THRU .061		+.036 -.033		+.036 -.033																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.061 THRU .062		+.037 -.034		+.037 -.034																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.062 THRU .063		+.038 -.035		+.038 -.035																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.063 THRU .064		+.039 -.036		+.039 -.036																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.064 THRU .065		+.040 -.037		+.040 -.037																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.065 THRU .066		+.041 -.038		+.041 -.038																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.066 THRU .067		+.042 -.039		+.042 -.039																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.067 THRU .068		+.043 -.040		+.043 -.040																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.068 THRU .069		+.044 -.041		+.044 -.041																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.069 THRU .070		+.045 -.042		+.045 -.042																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.070 THRU .071		+.046 -.043		+.046 -.043																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.071 THRU .072		+.047 -.044		+.047 -.044																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.072 THRU .073		+.048 -.045		+.048 -.045																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.073 THRU .074		+.049 -.046		+.049 -.046																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.074 THRU .075		+.050 -.047		+.050 -.047																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.075 THRU .076		+.051 -.048		+.051 -.048																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.076 THRU .077		+.052 -.049		+.052 -.049																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.077 THRU .078		+.053 -.050		+.053 -.050																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.078 THRU .079		+.054 -.051		+.054 -.051																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.079 THRU .080		+.055 -.052		+.055 -.052																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.080 THRU .081		+.056 -.053		+.056 -.053																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.081 THRU .082		+.057 -.054		+.057 -.054																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.082 THRU .083		+.058 -.055		+.058 -.055																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.083 THRU .084		+.059 -.056		+.059 -.056																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.084 THRU .085		+.060 -.057		+.060 -.057																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.085 THRU .086		+.061 -.058		+.061 -.058																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.086 THRU .087		+.062 -.059		+.062 -.059																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.087 THRU .088		+.063 -.060		+.063 -.060																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.088 THRU .089		+.064 -.061		+.064 -.061																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.089 THRU .090		+.065 -.062		+.065 -.062																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.090 THRU .091		+.066 -.063		+.066 -.063																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.091 THRU .092		+.067 -.064		+.067 -.064																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.092 THRU .093		+.068 -.065		+.068 -.065																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.093 THRU .094		+.069 -.066		+.069 -.066																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.094 THRU .095		+.070 -.067		+.070 -.067																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.095 THRU .096		+.071 -.068		+.071 -.068																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.096 THRU .097		+.072 -.069		+.072 -.069																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.097 THRU .098		+.073 -.070		+.073 -.070																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.098 THRU .099		+.074 -.071		+.074 -.071																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.099 THRU .100		+.075 -.072		+.075 -.072																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.100 THRU .101		+.076 -.073		+.076 -.073																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.101 THRU .102		+.077 -.074		+.077 -.074																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.102 THRU .103		+.078 -.075		+.078 -.075																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.103 THRU .104		+.079 -.076		+.079 -.076																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.104 THRU .105		+.080 -.077		+.080 -.077																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.105 THRU .106		+.081 -.078		+.081 -.078																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.106 THRU .107		+.082 -.079		+.082 -.079																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.107 THRU .108		+.083 -.080		+.083 -.080																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.108 THRU .109		+.084 -.081		+.084 -.081																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.109 THRU .110		+.085 -.082		+.085 -.082																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.110 THRU .111		+.086 -.083		+.086 -.083																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.111 THRU .112		+.087 -.084		+.087 -.084																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.112 THRU .113		+.088 -.085		+.088 -.085																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.113 THRU .114		+.089 -.086		+.089 -.086																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.114 THRU .115		+.090 -.087		+.090 -.087																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.115 THRU .116		+.091 -.088		+.091 -.088																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.116 THRU .117		+.092 -.089		+.092 -.089																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.117 THRU .118		+.093 -.090		+.093 -.090																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.118 THRU .119		+.094 -.091		+.094 -.091																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.119 THRU .120		+.095 -.092		+.095 -.092																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.120 THRU .121		+.096 -.093		+.096 -.093																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.121 THRU .122		+.097 -.094		+.097 -.094																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.122 THRU .123		+.098 -.095		+.098 -.095																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.123 THRU .124		+.099 -.096		+.099 -.096																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.124 THRU .125		+.100 -.097		+.100 -.097																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.125 THRU .126		+.101 -.098		+.101 -.098																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.126 THRU .127		+.102 -.099		+.102 -.099																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.127 THRU .128		+.103 -.100		+.103 -.100																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.128 THRU .129		+.104 -.101		+.104 -.101																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.129 THRU .130		+.105 -.102		+.105 -.102																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.130 THRU .131		+.106 -.103		+.106 -.103																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.131 THRU .132		+.107 -.104		+.107 -.104																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.132 THRU .133		+.108 -.105		+.108 -.105																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.133 THRU .134		+.109 -.106		+.109 -.106																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.134 THRU .135		+.110 -.107		+.110 -.107																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.135 THRU .136		+.111 -.108		+.111 -.108																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.136 THRU .137		+.112 -.109		+.112 -.109																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.137 THRU .138		+.113 -.110		+.113 -.110																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.138 THRU .139		+.114 -.111		+.114 -.111																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.139 THRU .140		+.115 -.112		+.115 -.112																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.140 THRU .141		+.116 -.113		+.116 -.113																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.141 THRU .142		+.117 -.114		+.117 -.114																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.142 THRU .143		+.118 -.115		+.118 -.115																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.143 THRU .144		+.119 -.116		+.119 -.116																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.144 THRU .145		+.120 -.117		+.120 -.117																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.145 THRU .146		+.121 -.118		+.121 -.118																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.146 THRU .147		+.122 -.119		+.122 -.119																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.147 THRU .148		+.123 -.120		+.123 -.120																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.148 THRU .149		+.124 -.121		+.124 -.121																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.149 THRU .150		+.125 -.122		+.125 -.122																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.150 THRU .151		+.126 -.123		+.126 -.123																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.151 THRU .152		+.127 -.124		+.127 -.124																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.152 THRU .153		+.128 -.125		+.128 -.125																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.153 THRU .154		+.129 -.126		+.129 -.126																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.154 THRU .155		+.130 -.127		+.130 -.127																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.155 THRU .156		+.131 -.128		+.131 -.128																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.156 THRU .157		+.132 -.129		+.132 -.129																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.157 THRU .158		+.133 -.130		+.133 -.130																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.158 THRU .159		+.134 -.131		+.134 -.131																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.159 THRU .160		+.135 -.132		+.135 -.132																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.160 THRU .161		+.136 -.133		+.136 -.133																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.161 THRU .162		+.137 -.134		+.137 -.134																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.162 THRU .163		+.138 -.135		+.138 -.135																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.163 THRU .164		+.139 -.136		+.139 -.136																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.164 THRU .165		+.140 -.137		+.140 -.137																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.165 THRU .166		+.141 -.138		+.141 -.138																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.166 THRU .167		+.142 -.139		+.142 -.139																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.167 THRU .168		+.143 -.140		+.143 -.140																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.168 THRU .169		+.144 -.141		+.144 -.141																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.169 THRU .170		+.145 -.142		+.145 -.142																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.170 THRU .171		+.146 -.143		+.146 -.143																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.171 THRU .172		+.147 -.144		+.147 -.144																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.172 THRU .173		+.148 -.145		+.148 -.145																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.173 THRU .174		+.149 -.146		+.149 -.146																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.174 THRU .175		+.150 -.147		+.150 -.147																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.175 THRU .176		+.151 -.148		+.151 -.148																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.176 THRU .177		+.152 -.149		+.152 -.149																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.177 THRU .178		+.153 -.150		+.153 -.150																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.178 THRU .179		+.154 -.151		+.154 -.151																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.179 THRU .180		+.155 -.152		+.155 -.152																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.180 THRU .181		+.156 -.153		+.156 -.153																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.181 THRU .182		+.157 -.154		+.157 -.154																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.182 THRU .183		+.158 -.155		+.158 -.155																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.183 THRU .184		+.159 -.156		+.159 -.156																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.184 THRU .185		+.160 -.157		+.160 -.157																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.185 THRU .186		+.161 -.158		+.161 -.158																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.186 THRU .187		+.162 -.159		+.162 -.159																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.187 THRU .188		+.163 -.160		+.163 -.160																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.188 THRU .189		+.164 -.161		+.164 -.161																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.189 THRU .190		+.165 -.162		+.165 -.162																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.190 THRU .191		+.166 -.163		+.166 -.163																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.191 THRU .192		+.167 -.164		+.167 -.164																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.192 THRU .193		+.168 -.165		+.168 -.165																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.193 THRU .194		+.169 -.166		+.169 -.166																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.194 THRU .195		+.170 -.167		+.170 -.167																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.195 THRU .196		+.171 -.168		+.171 -.168																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.196 THRU .197		+.172 -.169		+.172 -.169																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.197 THRU .198		+.173 -.170		+.173 -.170																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.198 THRU .199		+.174 -.171		+.174 -.171																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.199 THRU .200		+.175 -.172		+.175 -.172																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.200 THRU .201		+.176 -.173		+.176 -.173																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.201 THRU .202		+.177 -.174		+.177 -.174																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.202 THRU .203		+.178 -.175		+.178 -.175																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.203 THRU .204		+.179 -.176		+.179 -.176																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.204 THRU .205		+.180 -.177		+.180 -.177																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.205 THRU .206		+.181 -.178		+.181 -.178																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.206 THRU .207		+.182 -.179		+.182 -.179																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.207 THRU .208		+.183 -.180		+.183 -.180																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.208 THRU .209		+.184 -.181		+.184 -.181																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.209 THRU .210		+.185 -.182		+.185 -.182																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.210 THRU .211		+.186 -.183		+.186 -.183																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.211 THRU .212		+.187 -.184		+.187 -.184																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.212 THRU .213		+.188 -.185		+.188 -.185																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.213 THRU .214		+.189 -.186		+.189 -.186																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.214 THRU .215		+.190 -.187		+.190 -.187																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.215 THRU .216		+.191 -.188		+.191 -.188																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.216 THRU .217		+.192 -.189		+.192 -.189																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.217 THRU .218		+.193 -.190		+.193 -.190																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.218 THRU .219		+.194 -.191		+.194 -.191																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.219 THRU .220		+.195 -.192		+.195 -.192																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
.220 THRU .221		+.																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																													




Figure 59




Figure 60

THIS REPORT HAS BEEN DELIMITED
AND CLEARED FOR PUBLIC RELEASE
UNDER DOD DIRECTIVE 5200.20 AND
NO RESTRICTIONS ARE IMPOSED UPON
ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE,
DISTRIBUTION UNLIMITED.